



## THERMAL SPRAY & MANUFACTURING TECHNOLOGY SDN BHD

No. 14 JALAN UTARID U5/21 (P5), SEKSYEN U5 PANASURIA, 40150 SHAH ALAM, SELANGOR. (HQ)  
LOT 34094, TGKT BWH, KG PADANG TEPOH, JLN KELANTAN, 21060 KUALA NERUS, TERENGGANU (BRANC)  
TEL:03-78474171 FAX:03-78468968 E-MAIL: thermal\_spraysb@yahoo.com



Galaxy Aerospace (M) Sdn Bhd  
Suite 11-14, MRO Centre,  
Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport,  
47200 Subang, Selangor.

### REVISED QUOTATION

No.: GA02/23

Date: 20/10/2023

Terms of Payment: As Below

Validity: 15 Days

| Item No. | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Quantity (Unit) | Unit Price (RM/Unit) | Amount (RM) |
|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|----------------------|-------------|
| 1        | To repair by welding on spare Helicopter's Fuel Tank leaking, Job consist of:<br>a) to visual inspection at the crack and do marking<br>b) to cut the tank round (welded area) at one side for access at welding and to clean affected area<br>c) welding both side (inside & outside) the crack area and if necessary to do patch repair welding<br>d) to weld back round tank<br>e) FPI test after welding<br>f) do the pressure test after welding<br>g) re-paint rework area as per original colour<br><br><b>Note:</b><br>- Deposit 50% after received order<br>- Balance 50% after 30 days after delivery | lump sum        | 12,000.00            | 12,000.00   |
|          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |                 |                      | 12,000.00   |

We hope the above price will meet your kind consideration and looking forward to your favorable reply.

Above quotation accepted by

  
NURULAZHAN B. SALLEHUDDIN  
Senior Maintenance Manager (SMM)  
Galaxy Aerospace (M) Sdn Bhd  
(1040262-D)

TSMT Sdn. Bhd.

*Zulkifli Ismail*

Authorised Signature