



QUOTATION

G7 AEROSPACE SDN BHD

523830-H

A-2-01 CoPlace 1
2270 Jalan Usahawan 2
63000 Cyberjaya, Selangor
Malaysia
Phone (603) 8322 6393 Fax (603) 8322 6693

To:
GALAXY AEROSPACE (m) SDN BHD
Suite 11-14, Helicopter Center,
Malaysia International Aerospace Center
Sultan Abdul Aziz Shah Airport,
47200 SUBANG Selangor

Date : 09/08/2023

Quotation No: G7/QTN/023-23 R1

Prepared by : Mohd Sani

REPAIR QUOTATION

Item : CENTRAL WARNING PANEL (CWP)

Part Number : 80-0700-9

Serial Number : 100

REPORT:

Owner of Defective Item: Galaxy Aerospace

Initial Defect: INTAKE 1 TEMP. NOT ILLUMINATED

Tear down inspection carried out and found:

Initial functional test carried out found:

- The item was received to be in good condition after a visual and physical inspection.

Item was externally cleaned and disassembled so that component per component troubleshooting and fault isolation detection was carried out and the following were found:

- Unit disassembled, all components on each assembly inspected and examine and found wire No. 37 chafing to the body
- Further unit testing carried out found some of display not illuminate and some of display dim
- Annunciator display disassembled and inspection carried out found:
 - 1) One of the lighting bulb pairs blown out and this condition causes the display was dimmed.
 - 2) Terminal bezel found not contacted to display and this condition causes the display not illuminate.
 - 3) Some of terminal bezel contaminated with dust and need to be cleaned.
- Contacts of terminal bezel repaired as per required and found annunciator illuminated
- All parts to be cleaned and defective LED bulb need to be replaced.

Rectification Plan:

- a. Unit to be repaired and defective bulbs to be replaced.
- b. Testing to be carried out after repaired.
- c. Carry out loose article checks to ensure all parts are accounted for.
- d. Carry out continuity check to ensure no any shorting.
- e. Clean all parts from dirt and rust.
- f. Reassemble the unit as an assembly.
- g. Reapply conformal coating.
- h. Functional test the unit within a set duration of time to ensure stability of repair.
- i. Quality checks to ensure check and balance of items.

SERVICE COST:

No.	DESCRIPTION	AMOUNT (RM)
1.	Receipt, Tear Down Inspection and Testing	5,850.00
2.	Repair Services	12,000.00
3.	Reassembly	750.00
4.	Pre-test & Final Testing	1,200.00
5.	Spare Part	4,600.00
6.	Consumable Part	350.00
SUBTOTAL		24,750.00
TOTAL		24,750.00

SPARE PART

NO	DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL
1	LED BULB	20	115.00	2300.00
2	LED BULB (spare)	20	115.00	2300.00
TOTAL				4,600.00

CONSUMABLE PART

NO	DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL
1	CONTACT CLEANER	1	125.00	125.00
2	ISOPROPYL ALCOHOL	1	50.00	50.00
3	ARALDITE	1	50.00	50.00
4	SILICON GLUE	1	125.00	125.00
TOTAL				350.00

Notes:

- 1) The quotation is valid for 30 days from quotation issuance.
- 2) Prices are based on effective price list at the date of quotation and maybe subject to variation.
- 3) Lead Time : 30 Days from receipt of quotation acceptance.
- 4) Payment Terms : 30 days after invoice issued.
- 5) G7 Aerospace Bank Details:

Bank Name : **CIMB Bank Berhad**
Bank Address : **Prima 5-A, Jalan Teknokrat 5, 63000 Cyberjaya, Selangor, Malaysia**
Account Name : **G7 Aerospace Sdn Bhd**
Account Number : **8003225779**
Bank Swift Code : **CIBBMYKL**

Please contact us should you have any questions concerning this quotation, contact name, phone number.

For and on behalf,
G7 Aerospace Sdn Bhd



Mohd Sani bin Muhamad Yunos
Operations Manager

THANK YOU FOR YOUR BUSINESS!