



QUOTATION

G7 AEROSPACE SDN BHD

523830-H

A-2-01 CoPlace 1
2270 Jalan Usahawan 2
63000 Cyberjaya, Selangor
Malaysia
Phone (603) 8322 6393 Fax (603) 8322 6693

To: GALAXY AEROSPACE (m) SDN BHD Suite 11-14, Helicopter Center, Malaysia International Aerospace Center Sultan Abdul Aziz Shah Airport, 47200 SUBANG Selangor	Date : 20/5/2024 Quotation No: G7/QTN/038-24 <i>Prepared by :</i> Mohd Sani
--	---

REPAIR QUOTATION

Item : Electronic Display Unit

Part Number : 597-2247-001

Serial Number : 1184

REPORT:

Owner of Defective Item: Galaxy Aerospace (m) SDN BHD

Initial Defect: EDU fan malfunction

Visual inspection and initial testing carried out and found:

- Preliminary testing carried out IAW G7A-MRO-WI-105 Work Instruction for Electronic Display Unit Para 9.1, found fan moved in a short time but stopped instantly and won't rotate.

Item was disassembled so that component per component troubleshooting and fault, found:

1. Fan assembly disassembled, continuity check carried out and found:
 - Fan shorting and confirm defective
 - Fan to be replaced
2. Unit disassembled, inspected and troubleshooting carried out on all sub-assembly by testing the functionality of the components on sub assembly.
 - Using multimeter, the values of all passive components were found to be within tolerance.
 - Using component checker, the condition of active components is checked and found to be satisfactory.
3. Inspection for loose wire, burned or fried insulator, and worn-out wire was carried out and found satisfactory.
4. Inspection for corrosion, wear or damage on all parts were carried out and found satisfactory.

Rectification Plan:

- Defective fan needs to be replaced.
- Testing to be carried out after replacement of fan assembly.
- Carry out continuity check on all parts to ensure no any shorting.
- Clean all components of dirt and rust.
- Reassemble all components after inspected, checked, and cleaned.
- Perform a loose article check on all components to ensure they are all accounted for.
- To carry out functional test within a set duration of time to ensure functionality after repair.
- Quality checks to ensure check and balance of items.

SERVICE COST:

No.	DESCRIPTION	AMOUNT (RM)
1.	Receipt, Tear Down Inspection and Testing	1,050.00
2.	Repair Services	600.00
3.	Reassembly	300.00
4.	Pre-test & Final Testing	4,200.00
5.	Spare Part	270.00
	SUBTOTAL	6,420.00
	TOTAL	6,420.00

Notes:

- 1) The quotation is valid for 30 days from quotation issuance.
- 2) Prices are based on effective price list at the date of quotation and maybe subject to variation.
- 3) Lead Time : 30 Days from receipt of quotation acceptance.
- 4) Payment Terms : 30 days after invoice issued.
- 5) G7 Aerospace Bank Details:

Bank Name : **CIMB Bank Berhad**
Bank Address : **Prima 5-A, Jalan Teknokrat 5, 63000 Cyberjaya, Selangor, Malaysia**
Account Name : **G7 Aerospace Sdn Bhd**
Account Number : **8003225779**
Bank Swift Code : **CIBBMYKL**

Please contact us should you have any questions concerning this quotation, contact name, phone number.

For and on behalf,

G7 Aerospace Sdn Bhd



Mohd Sani bin Muhamad Yunos

Operations Manager

THANK YOU FOR YOUR BUSINESS!