

# QUOTATION



**Galaxy Aerospace (M) Sdn. Bhd.**  
Suite 11-14, Helicopter Centre,  
Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport,  
47200 Subang, Selangor

Date 18.06.2021  
Page 1 / 3  
Contact Wilson Tan  
Phone +6012 3710 596  
Email [wilson.tan@ruag.com](mailto:wilson.tan@ruag.com)

Attn: Ms. Nor Izzati Azmi

**Customer No: GAM1060KL**  
**Quotation No RAIM-001000**

Valid until	Terms of payment	Terms of delivery	Remarks
17.07.2021	30 days net	EXW (Subang)	

## REPAIR OF ONE (1) UNIT STARTER-GENERATOR P/N 160SG139Q-2 S/N 1575XL2

Dear Ms. Ms. Nor Izzati Azmi

We are pleased to submit our quotation for the repair of search light as following:

Item	Quantity	Description	Price per Unit (USD)	Amount (USD)
1	1 EA	<b>STARTER-GENERATOR</b> <b>P/N: 160SG139Q-2</b> <b>S/N: 1575XL2</b> Removal reason: Smoke during crank Scope of work: Repair and test. Replace speed pick up.	RPR 4,350.00 (MYR 18,285.23)	<b>4,350.00</b> <b>(MYR 18,285.23)</b>

### Teardown/Condition findings:

1. Unit failed bar to bar check. Therefore requires to be stripped completely in order to refurbish.
2. Bearing change required upon removal of commutator.
3. Speed pick up (300SG1222-2) sensor face worn beyond limit. Require replacement with new.
4. Armature (160SG1064) found retaining bands loose. Require repair.

Total Items	<b>4,350.00</b>
TOTAL	<b>(MYR 18,285.23)</b>

Home:	Division:	Group:
<b>RUAG Aviation Malaysia</b>	<b>RUAG Aviation</b>	<b>RUAG Switzerland Ltd.</b>
Lot 1-4, Ex Customs Building	Subsystem and Products	Seetalstrasse 175
Helicopter Center	P.O. Box 501	P.O. Box 301
Malaysia International Aerospace Center	3800 Interlaken	6032 Emmen
Sultan Abdul Aziz Shah Airport	Switzerland	Switzerland
47200 Subang, Selangoe	www.ruag.com	
Malaysia		

# QUOTATION

**Galaxy Aerospace (M) Sdn. Bhd.**  
Suite 11-14, Helicopter Centre,  
Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport,  
47200 Subang, Selangor

Date 18.06.2021  
Page 2 / 3  
Contact Wilson Tan  
Phone +6012 3710 596  
Email [wilson.tan@ruag.com](mailto:wilson.tan@ruag.com)

Attn: Ms. Nor Izzati Azmi

**Customer No: GAM1060KL**  
**Quotation No RAIM-001000**

Valid until	Terms of payment	Terms of delivery	Remarks
17.07.2021	30 days net	EXW (Subang)	

## REPAIR OF ONE (1) UNIT STARTER-GENERATOR P/N 160SG139Q-2 S/N 1575XL2

Dear Ms. Ms. Nor Izzati Azmi

We are pleased to submit our quotation for the repair of search light as following:

Item	Quantity	Description	Price per Unit (USD)	Amount (USD)
------	----------	-------------	----------------------	--------------

### Material require replacement:

<u>Part No.</u>	<u>Description</u>	<u>Qty</u>	<u>Part No.</u>	<u>Description</u>	<u>Qty</u>
<b>High Cost Parts:</b>					
300SG1222-2	SPEED PICKUP	1 Iss.			
<b>Std., 100% &amp; Misc. Parts:</b>					
150SG1052-14	BEARING	2 Iss.	150SG1070	FRICTION RING	1 Iss.
150SG1071	NUT	1 Iss.	150SG1092-29011	SUPPLEMENTAL LABEL	1 Iss.
150SG1093	SPRING	2 Iss.	150SG1139	DECAL	1 Iss.
150SG1168	DECAL	1 Iss.	150SG1379-8	WASHER	20 Iss.
150SG1389-3	NUT	2 Iss.	150SG1389-6	NUT	2 Iss.
200SGL1360-1S	SAI - XL2 LABEL	1 Iss.	M83248-1-113	SEAL	1 Iss.
MS16624-4066	RETAINING RING	1 Iss.	MS35338-43	WASHER	2 Iss.

Total Items				
TOTAL				

Home:

**RUAG Aviation Malaysia**

Lot 1-4, Ex Customs Building

Helicopter Center

Malaysia International Aerospace Center

Sultan Abdul Aziz Shah Airport

47200 Subang, Selangoe

Malaysia

Division:

**RUAG Aviation**

Subsystem and Products

P.O. Box 501

3800 Interlaken

Switzerland

[www.ruag.com](http://www.ruag.com)

Group:

**RUAG Switzerland Ltd.**

Seetalstrasse 175

P.O. Box 301

6032 Emmen

Switzerland

Date 18.06.2021  
Page 3 / 3

**Quotation No** RAIM-001000

**Terms of payment**

30 days after receipt all related documents.

**Terms of shipping**

EXW (Incoterms 2010) RAIM Subang

**Quality Standard**

EASA Form 1

**Warranty**

RAIM warrants that the items supplied have the properties specified have not physical or legal defects or defects that limit their to extended function. The terms of warranty for repair is 6 months from the date of the transfer of risk or 500 flight hours whichever come first. Excluded from the warranty are defects caused by improper use, inadequate maintenance, overloading or any other causes that are beyond the control of RUAG.

**Exclusion**

**Others**

RAIM maintains a scrap policy where unless requested otherwise by customer in writing, all unserviceable parts will be scrapped on site 3 months after close of work order.

The performance is subject to the provision that RUAG is not hindered in its supply chain or performance by the current difficult situation worldwide due to the corona pandemic. RUAG cannot exclude this from today's perspective. Any liability of RUAG for damages resulting from this is excluded to the extent permitted by law.

**General terms and conditions**

For all items not mentioned in this agreement, please refer to our GTC enclosed dated August 2019, which are an integrated part of this quotation.

We trust our proposal meets your requirements.

Wilson Tan  
**Sales & Marketing Manager**

Wan Aida  
**Executive - Admin**

**Enclosure;**

1. General Terms and Conditions (GTC SMS MY Edition August 2019)