



CHOPPERTECH SERVICES SDN BHD (1161592-X)

No.38 & 38-1, JALAN TPS 1/7
TMN PELANGI SEMENYIH
43500 SEMENYIH, SELANGOR
MALAYSIA.
TEL: +6016-8402775.
FAX NO. +603-21784881

QUOTATION

Quotation ref.no.:	QUO/CTS/AERO/2021/003 Rev 1	Date:	May 2021
Your order ref.no.:	PO-21-2247	CTS GST Number	000068694016

BILL TO:- Galaxy Aerospace (M) Sdn. Bhd. Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	CONTACT:- Attn.: Nor Azman
--	--------------------------------------

Item	Part Number	Description	Unit Price (RM)	Qty	Price (RM)	Lead Time
1.	10406-20600-1	Control Electric Unit SN1001	49,590.00	1	49,590.00	150 Days
2.	10406-20600-1	Control Electric Unit Sn1002 Repair	39,150.00	1	39,150.00	150 Days
3.	10406-06410/1	Stabilized Turret Unit LEO II(STU) SN 1000 Return for Repair	78,300.00	1	78,300.00	150 Days
4.	-	Freight to SA and back to KL after Repair	6,500.00	2	13,000.00	-
5	-	Insurance cover RM2.2mil to SA and back to KL after Repair	4,080.00	2	8,160.00	-
TOTAL					188,200.00	

Note:

1. Payment : Full payment upon purchase order issued.
2. Quote Validity : 30 Days/price might change depend on currency, final freight charges and taxes.
3. Insurance coverage: Client is required to inform the amount of items that they wish to insure. Without any confirmation from client, our company will automatically insure the items based on the items repair value. If client wish to insure more than the items repair value, client would need to bear the extra insurance cost.
4. Sales Condition : In case of rejection of final repair quotation, **TT&E Fee** will be charged per unit and will be returned as **disassembled condition**. TT&E Fee will become void once repair estimate is provided and approved. A final repair quotation will be submitted to customer's consideration for approval after TDI.
5. Warranty: 6 months (Term & conditions apply).
6. Delivery Lead time: Is estimation, might affect spare availability and condition of the core unit been send for repair or overhaul. Field repair schedule might no affected by MCO regulations that set by our government and origin country regulations

FOR: CHOPPERTECH SERVICES SDN. BHD.

Mr. Robin Chin

Managing Director

E-MAIL: rbnchinyt@gmail.com

Tel: +6016-8402775