

YES

 \square

406 Dividend Drive Peachtree City, Georgia 30269 Phone (770) 632-1851 Fax: (770) 632-1852

Repair Estimate

	DATE:	26-Apr-2022	
	PRIME REFERENCE:	051193	
NO	CUSTOMER REFERENCE:	RMN-22-305	
	PART NUMBER:	CP1976FB01	
\checkmark	SERIAL NUMBER:	5238	
\checkmark	DESCRIPTION:	SELECTOR SWITCH, TB31	
\checkmark	WORK REQUESTED:	REPAIRED	

EVALUATIONS / FINDINGS:

SPECIAL INSTRUCTION:

PRELIMINARY INSPECTION: UNIT REQUIRES CONFIGURATION. LOW LEVELS HI IMPEDANCE. (BNH2) AUDIO OUTPUT DISTORTION. IES POT BROKEN AND FACE PLATE IS MISSING LEFT ER.

TEARDOWN FINDING: IES POT AND KNOB HAS FAILED, NEED TO REPLACE. SOME CAPACITORS ARE OLD DUE TO AGE, RECOMMEND REPLACEMENT.

CORRECTIVE ACTIONS TO BE CARRIED OUT:

REPAIR REQUIRED

LOG CARD:

PICTURES:

UNIT MISUSED:

PARTS REPLACED OR REPAIRED

EXCLUSIONS:	NO	CONDITION AFTER COMPLETION:		REPAIRED	
PART NUMBER	DESCRIPTI	ON	STATUS	QUANTITY	PRICE
FLAT RATE:	\$2,856.00		COMMENTS:		
TOTAL QUOTE					
TOTAL QUOTE OPTION #1					
TURN AROUND TIME AFTER APPROVAL: (IN BUSINESS DAYS)	120-150	A	pproval Signature:		
EVALUATION FEE IF QUOTE DENIED	\$775.00	Na	ime:	Da	ite: