



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

No. 5608477 Pg:1/1

GALAXY AEROSPACE (M) SDN BHD
 Attn: MUZDALIFAH HANANI ROSLIZAN
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +60377347226

Our Ref : SO# 5604745
Your Ref : MMA-23-882
Terms : PREPAID WIRE TRANSFR
Our Contact : Ratan Pandey
eMail : rpandey@heliparts.com
Valid Until : Jun-28-2024
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : May-29-2024

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	418-00475-550 BAROMETER MODULE Serial No(s): 2564 ECCN: 9A991.d Reported By Customer: UNIT IS INOP. INSPECT AND ADVISE Preliminary Inspection: UNIT RECEIVED IN FAIR EXTERIOR CONDITION UNIT FAILED INCOMING TEST REQUIRES REPLACEMENT OF PRESSURE SEALS - USD 2,715.00 REWORK OF ANEMOMETRIC CURVE OUTPUT VALUES - USD 3,495.00 REWORK OF BAROMETRIC CURVE OUTPUT VALUES - USD 3,495.00 REWORK OF BAROMETRIC SYNCHRO RESIDUALS AND ANEMOMETRIC COMMUTATION - USD 4,725.00 UNIT REQUIRES STANDARD REPAIR - USD 15,950.00 TOTAL - USD 30,380.00 Corrective Action: UNIT WILL BE REPAIRED AS PER CMM AND TESTED TO PASS ALL FUNCTIONS. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature: _____ Date: _____	RP	1 EA	45 Days	\$ 30,380.00 EA	\$ 30,380.00

Sub Total:	\$ 30,380.00
Total: [USD]	\$ 30,380.00

 RIDZUAN BIN YA'AKOB,