

STRIP REPORT

Goodrich Corporation
4115 Corporate Center Drive
MONROE NC 28110-1313
USA
Repair Station #G84R924X-EASA#5617



Customer SOLID PARTNERS SDN BHD	Cust PO 002537		
Input Part 44316-12-104	Input Serial 40477	Qty 1.000	
Output Part	Output Serial	Workscope REPAIR	
Cust Part 3G2591V01532	Cust Serial	Status/Work REPAIRED	
Description RESCUE HOIST ASSY DC PWD	Removal Code	Failure Date	
Aircraft Misc	Engine Type		
Incoming NSN N/A	Outgoing NSN N/A	Tail No	
Date Rec'd 07/18/2023	Quote Date	Accept Date	
Ship Date	DOM		
Sales Order 120820245	Work Order 45666093	Notification 305284984	

Customer Reason for Return

RESCUE HOIST DUE FOR CLUTCH REPLACEMENT

Previous Work History

NO PREVIOUS HISTORY

Conditions

Preliminary Inspection

Received Date: 07/18/2023 Inducted: 08/14/2023
ID Plate P/N: 44316-12-104 S/N: 40477
Vibroscribed P/N:44316-12-104 S/N: 40477
Damage to Container or Unit: NONE
Missing or Damaged Parts: FAIRING WINDOW CRACKED
Fairing's Received: YES
1. 42316-153
2. 44316-151
3. 44311-128
4. 42325-128
Cartridge Removed: YES
Meter Reading: 021.2 (HOURS & TENTHS)
COLOR: WHITE
Loose Hardware: NONE
LRU's Attached: YES
1. 44316-602-101 S/N 00337
Service Bulletins as Identified by the CRRT: ALL APPLICABLE
Customer Requested Requirements: TBD
Failure Analysis Report Required: TBD
Log Card Received: YES
Hook Received: YES
P/N: 42315-488
S/N: 3019

STRIP REPORT



Work Order	45666093	Description	RESCUE HOIST ASSY DC PWD	Date Rec'd	07/18/2023
Input Part	44316-12-104	Input Serial	40477		
Cust Part	3G2591V01532	Cust Serial			

Test Results

Unit was tested IAW the Testing and Fault Isolation section of CMM 25-60-06-3.
 Motor tests good at full load.

Evaluation Inspection

Unit was disassembled and inspected in accordance with the Disassembly and Check sections of CMM 25-60-06-3.
 All accessible critical parts were inspected in accordance with the critical parts inspection criteria. Refer to the attached strip report for a list of replaced components.

MINOR THREAD DAMAGE ON J3 MOTOR CONNECTOR (REPAIRED)

Service Bulletins - Outgoing

ASB44301-10-18 REV 6, OCT 10, 2016.

Work Performed

REPAIRED IAW CMM 25-60-06-3 REV. 2, MAY 24, 2016, EASA AD 2015-0226R7, EASA AD 2020-0026, SIL-2018-03 REV. 1, APR 03, 2018, AND SIL-2019-05 REV. 4, JUN 30, 2022.

Components :

Order	Material	Description	Req Qty	Issued	Reason Code	Stor Loc
45666093	44314-398-101	OVERLOAD CLUTCH ASSEMBLY	1	0	POP2 Clutch Replacement	NEW1
45666093	MS28775-168	PACKING, PREFORMED	1	0	CONSUMABLE	NEW1
45666093	MS28778-6	PACKING - PREFORMED	1	0	CONSUMABLE	NEW1
45666093	MS28778-4	O-RING - PREFORMED,351ID,.072,NBR	1	0	CONSUMABLE	NEW1
45666093	MS28778-8	O-RING	1	0	CONSUMABLE	NEW1
45666093	42325-298	CABLE,RESCUE HOIST	1	0	WORN	NEW1
45666093	NAS1081C3A5L	SETSCREW, SELFLOCKING	2	0	CONSUMABLE	NEW1
45666093	42315-190	SET SCREW, CABLE DRUM	1	0	CONSUMABLE	NEW1
45666093	NAS1096-2-6	SCREW HEX HEAD	25	0	CONSUMABLE	NEW1
45666093	NAS620C8L	WASH,FLAT,.169ID,.319OD,.016THK,SST/PSV	25	0	CONSUMABLE	NEW1

Goodrich Corporation
 4115 Corporate Center Drive
 MONROE NC 28110-1313
 USA
 Repair Station #G84R924X-EASA#5617

STRIP REPORT



Work Order	45666093	Description	RESCUE HOIST ASSY DC PWD	Date Rec'd	07/18/2023
Input Part	44316-12-104	Input Serial	40477		
Cust Part	3G2591V01532	Cust Serial			

45666093	NAS1096-3-8	BOLT, HEX	7	0	CONSUMABLE	NEW1
45666093	NAS620C10L	WASH,FLAT,.195ID,.354OD,.032THK,SST/P5V	7	0	CONSUMABLE	NEW1
45666093	MS28775-023	PACKING - PREFORMED (O-RING)	1	0	CONSUMABLE	NEW1
45666093	49000-207	PIN, SPRING	1	0	CONSUMABLE	NEW1
45666093	42325-128-7	POLYCARBONATE, CLEAR	1	0	CRACKED	NEW1
45666093	42315-441	GUIDE, CABLE	1	0	WORN	NEW1
45666093	MS24694-C50	SCREW, MACH, FLAT, 100D	4	0	CONSUMABLE	NEW1
45666093	42305-290	CYLINDER, ENERGY ABS	1	0	COMPRESSED	NEW1