



Scrap Blade Certificate	
Scrap Log Entry Number:	6

<i>Customer:</i>	Galaxy Aerospace	<i>Description:</i>	Tail Rotor Blade
<i>Part Number:</i>	709-0160-48-101	<i>Serial Number:</i>	P1532
<i>TSN:</i>	957.32	<i>Customer PO:</i>	4802498776
<i>Date:</i>	01 September 2021	<i>Reported Defect:</i>	Erosion Shield Dented

**The above blade has been inspected by Leonardo Malaysia and has been deemed SCRAP beyond repair for the following reason:**

Dent on the erosion shield is beyond allowable repair limits, with no repair scheme available from the OEM.

OEM has advised that the blade must be removed from service.

Name: Emlyn Williams

Signature:

A handwritten signature in blue ink that reads "Emlyn Williams".

Auth:

