

RMN-23-1031 / 355A32-0210-04 SN M358

Please find below quote for the repair of the above noted 355A32-0210-04 S/N M358 for your review & approval. TAT approximatively 30 days upon receipt of your quote approval.

Labor: \$8,800.00

Parts:

KIT-355A32-0210-XX SYSTEMATIC KIT	QTY 1	\$10,285.00	NEW
704A33-653-059 BEARING	QTY 3	\$4,500.00	OVERHAULED
355A75-1220-21 SUPPORT, LH	QTY 1	\$250.00	OVERHAULED
355A35-2029-20 BUSH	QTY 4	\$1,100.00	NEW
355A32-2089-21 BAFFLE	QTY 1	\$925.00	NEW
355A32-2005-03	QTY 1	\$27,850.00 ^{25,190}	NEW OVERHAULED
Parts Total:		\$44,910.00 42,250.00	

Outside Repairs:

355A32-2004-04 QTY 1 \$12,000.00

Note: Repair bolt holes qty 12.

Outside Repairs Total: \$12,000.00

Charges

Bench Stock/Material QTY 1 \$850.00

Test Bench Run In: QTY 1 \$1,100.00

Charges Total: \$1,950.00

TOTAL QUOTE:

~~\$67,860.00~~

\$65,000.00

Saving of \$2,660.00

RMN-23-1031 / 350A32-0110-00 SN M6615

Please find below quote for the repair of the above noted 350A32-0110-00 S/N M6615 for your review & approval. TAT approximatively 30 days upon receipt of your quote approval.

Labor: \$2,750.00

Parts:

KIT-350A32-0110/120-XX OVERHAUL SYSTEMATIC KIT	QTY 1	\$550.00	NEW
350A32-1089-21 MOUNT, PLANET GEAR	QTY 1	\$10,000.00 ^{2,750-}	SV (6,152 cycles remaining)
350A32-1082-03 PLANET GEAR ASSY	QTY 5	\$66,750.00	NEW
350A32-1075-20 GEAR, SUN	QTY 1	\$15,400.00 ^{#13,000-}	NEW SV
350A32-1119-20 RING GEAR	QTY 1	\$15,000.00	SV

Parts Total: ~~\$107,700.00~~ [#] 98,050-

Charges

Bench Stock/Material QTY 1 \$250.00

Charges Total: \$250.000

TOTAL QUOTE: ~~\$110,700.00~~

\$ 101,050.00

Saving of \$ 9,650.00

RMN-23-1031 / 355A32-0600-04 SN M5853

Please find below quote for the repair of the above noted 355A32-0600-04 S/N M5853 for your review & approval. TAT approximately 30 days upon receipt of your quote approval.

Labor: \$8,800.00

Parts:

KIT-355A32-0600-XX SYSTEMATIC KIT	QTY 1	\$19,380.00	NEW
704A34-629-011 STRAINER, FILLER PLUG	QTY 1	\$0.00	NEW
704A34-543-020 PLUG, ELECTRO MAGNET	QTY 1	\$3,105.00	NEW
704A33-653-002 BEARING	QTY 1	\$1,525.00	NEW
704A33-653-001 BEARING	QTY 1	\$2,188.00	NEW
355A32-2159-20 MGB Rear Exit Flange	QTY 1	\$6,525.00	NEW
355A32-2088-21 BAFFLE	QTY 1	\$1,135.00	OVERHAULED
355A32-2079-02 WHEEL	QTY 1	\$19,500.00	OVERHAULED
355A32-2039-20 SHIM	QTY 1	\$155.00	NEW
355A32201100 GEAR OIL PUMP DRIVER	QTY 1	\$2,650.00	OVERHAULED
350A32-5036-20 ROLLER	QTY 1	\$460.00	NEW
355A32-2021-01 Oil Pump Housing	QTY 1	\$0.00	

Parts Total: \$56,623.00

Outside Repairs:

350A32-3121-05 UPPER CASE QTY 1 \$11,890.00

Note: Repair upper flange lower surface with shim, Repair lower flange upper surface with shim, Repair upper and lower flange bolt holes.

350A32-3119-05 CASING ASSY, LOWER QTY 1 \$12,100.00

Note: Repair of lower surface of mount flange with shim, Repair of torque mount faces.

Outside Repairs Total: \$23,990.00

Charges

Bench Stock/Material QTY 1 \$850.00

Test Bench Run In: QTY 1 \$1,100.00

Charges Total: \$1,950.00

TOTAL QUOTE:

~~\$91,563.00~~

\$89,500.00

Saving of \$1,863.00