

## **REPAIR QUOTATION**

Leonardo Malaysia - Warehouse Lot 10, Jalan Teknologi, Taman Sains Selangor 1 Kota Damansara, 47810 Petaling Jaya Selangor Darul Ehsan

**Leonardo Malaysia Sdn Bhd** Lot 1 & 2 , Helicopter Center, Sultan Abdul Aziz Shah Airport 47200 Subang, Selangor Darul Ehsan, Malaysia

CUSTOMER GALAXY (SUPERLYNX)		REPAIR QUOTATION FOR MATERIAL RELATED TO YOUR ORDER					AW RMA		DATE	05.01.2023
							ISSUE N	400513610	OUR QUOTATION N.	
		ON DATE	22.12.2022						]	LM-537
							H	ERTIFICATION	DATE	05.01.2023
		CONTACT						COC		
GALAXY (SUPERLYNX)		OFFED VALIDITY					CUSTOME		CURRENCY	
		OFFER VALIDITY					SHIPPING		GBP PAYMENT TERM	IS
		Incoterms						WILTHOD		.0
		Ex Works							FDM2	
ITEM	SUPPLIABLE P/N - DESCRIPTION		UM	QUANTITY	S/N	UNIT PRIC	E	DISC %	TOTAL	ESTIMATED TAT DAY (*)
10	Part Number Received							/6		IAI DAI ()
	WG1369-0027-063			N	TAG1389	14,108.9	0			142
	DAMPER ASSY & EXTN. TUBE							_		
	Part Number to be Despatched									
	WG1369-0027-063 DAMPER ASSY & EXTN. TUBE				TAG1389					
	DAINI ER AGGT & EXTIV. TOBE									
	WORK DETAIL :									
	Overhaul									
		ACTIVITIES PRICE							14,108.90	
									_	
	(*) TAT calculation starts when the returned components is received, eveluated and considered eligible for repair, or from the acceptance of Leonardo Helicopter proposal by the Customer whichever occurs last.									
The above is not applicable if regulated by prior agreements executed between the Customer and Leonardo Helicopters .										
	Shipping Methods:	D 4								
	Payment Terms: FDM2 - 60days Billing	•	 	  1 bo ioa						
	This quotation is definitive , a revised repair quotation will be issued in case :  - during the repair activity it is nessasary to perform additional work or to replace other components not estimated at this st								s stage	
	Note: WE ARE WAITING FOR YOU		LIOIM AUDIT	LIONAL WOR	or to rebrace ofu	components n	ot estima	led at thi	s stage 	
	WORK REQUIRED : Overhaul	IN AFFROVAL								
1	VVOIN NEQUINED . OVEITIAUI									