



**Leonardo Malaysia Sdn Bhd**  
 Lot 1 & 2 , Helicopter Center,  
 Sultan Abdul Aziz Shah Airport  
 47200 Subang,  
 Selangor Darul Ehsan, Malaysia

## REPAIR QUOTATION

Leonardo Malaysia - Warehouse  
 Lot 10, Jalan Teknologi, Taman Sains Selangor 1  
 Kota Damansara, 47810 Petalín Jaya  
 Selangor Darul Ehsan

CUSTOMER GALAXY (SUPERLYNX)	REPAIR QUOTATION FOR MATERIAL RELATED TO YOUR ORDER RMN-21-11	AW RMA 20415824	DATE 08.08.2022
		ISSUE N 400501464	OUR QUOTATION N. LM-0361
SHIP TO GALAXY (SUPERLYNX)	ON DATE 29.07.2021	TYPE OF CERTIFICATION	DATE 08.08.2022
	CONTACT	CUSTOMER CODE 50009236	CURRENCY GBP
	OFFER VALIDITY	SHIPPING METHOD	PAYMENT TERMS FDM2
	Incoterms <b>Ex Works</b>		

ITEM	SUPPLIABLE P/N - DESCRIPTION	UM	QUANTITY	S/N	UNIT PRICE	DISC %	TOTAL	ESTIMATED TAT DAY (*)
10	Part Number Received WG1373-0020-049 TAIL ROTOR SERVO		N	FYH200827	81,738.70			135
	Part Number to be Despatched WG1373-0020-049 TAIL ROTOR SERVO			FYH200827				
	<b>WORK DETAIL :</b> REPAIR							
	<b>ACTIVITIES PRICE</b>						81,738.70	
<p>(*) TAT calculation starts when the returned components is received, evaluated and considered eligible for repair, or from the acceptance of Leonardo Helicopter proposal by the Customer whichever occurs last.            The above is not applicable if regulated by prior agreements executed between the Customer and Leonardo Helicopters .            Shipping Methods :            Payment Terms : FDM2 - 60days Billing Date            This quotation is definitive , a revised repair quotation will be issued in case :            - during the repair activity it is nessasary to perform additional work or to replace other components not estimated at this stage  <b>Note : WE ARE WAITING FOR YOUR APPROVAL</b>            WORK REQUIRED : OVERHAUL</p>								