PRELIMINARY TEARDOWN REPORT

Goodrich Actuation Systems SAS 43, rue des Pres F-27950 SAINT-MARCEL, VERNON Repair Station #O6SY947N



Input Serial Output Serial Cust Serial Removal Code	1933		1.000 OVERHAUL OVERHAULED
Cust Serial	1933	Status/Work	
			OVERHAULED
Removal Code	OVHL		
		Failure Date 05/18/2019	
	Engine Type		
Outgoing NSN N/A		Tail No	
Quote Date		Accept Date	
OOM	12/01/1999	Last Order Date	
Vork Order	44954007	Notification	n 304736928
כ	MOO	POM 12/01/1999	OOM 12/01/1999 Last Order

Preliminary TDR

REFERENCE CMM : DOC 65-40-01/3

REVISION: 19

AMENDMENTS IN: 02 03 AMENDMENTS OUT : 02 03 04

CERTIFICATIONS :

COLLINS

REMOVAL REASON :

IMPUTATION AND FAILURE CONFIRMATION :

OVERHAUL CHARGEABLE TO CUSTOMER

PRIMARY FAULT :

REAR BEARING LEAK

PISTON LEAKAGE FRONT PA (DEEP SCRATCH ON PISTON PA => UNSERVICEABLE)

UNSTABLE DRIFT LIMIT SPEED

CONTROL EFFORT OUT OF TOLERANCE

DEAD STROKE OUT OF TOLERANCE

AUTHORITY PA OUT OF TOLERANCE

WORK PERFORMED :

OVERHAULED

Printed on 07/29/2022 06:09:38

Page 1 of 2

Goodrich Actuation Systems SAS 43, rue des Pres F-27950 SAINT-MARCEL, VERNON Repair Station #06SY947N

PRELIMINARY TEARDOWN REPORT



Work Order	44954007	Description	OFD) (O. o.		
Input Part	30495-211	Description	SERVOCONTROL	Date Rec'd	06/22/2022
put rait	30495-211	Input Serial	1933		
Cust Part		Cust Serial	1933		

Author : Print name : Signature: Date:

G. LECOUR 29 JUL 2022

Authorized Approval :

Signature: Date:

Collins Aerospace Saint-Marcel site is pleased to provide this quote to service the subject item. In order to serve you better,

Collins Aerospace Saint-Marcel site reserves the right to stop work and requote if further processing show any previously undetected fault or damage condition.

Printed on 07/29/2022 06:09:38

Form No. GR001171-0513

Page 2 of 2