



Repair Estimate

Sold To: 77560
Galaxy Aerospace (M) Sdn Bhd
Customer PO # : PO-24-8073

Date: 2024.08.24
SAP Repair Sales Order # : 6449866
PWCS PO #: 4504977287
From: SARAH CONKLIN

Ref/WO#:
Core Disposition

PWCS JR3-0105-E (2014-06)

<u>Part Number</u>	<u>Serial No</u>	<u>Qty</u>	<u>Comments/Repair Required</u>	<u>Disposition</u>	<u>Estimate USD</u>
62129-01	15035190	1	REPAIR FINDINGS : PART WAS DEEMED UNSERVICABLE. OPTION 1 : REPLACEMENT \$ 32,156.74 USD NEW UNIT RETURNING IS 62129-03 OR OPTION 2 SCRAP PART FOR \$844.41	HD	\$32,156.74

Subtotal \$32,156.74
Sales Tax \$0.00
Total \$32,156.74

Customer Approval Signature: _____ **Date :** _____

The success of this repair which has been quoted is limited by any hidden characteristics not detectable at detail inspection (eg: any previous rework that may result in insufficient material remaining to continue repair). Part may be declared unrepairable/unserviceable. All costs incurred to the point of being determined "unserviceable" will be charged to the customer. Price indicated is based on the identified work scope. Unforeseen conditions discovered during repair requiring additional work will be immediately communicated to the customer with revised pricing. The part turn time may be affected.



Repair Estimate

Sold To: 77560
Galaxy Aerospace (M) Sdn Bhd
Customer PO # : PO-24-8074

Date: 2024.08.24
SAP Repair Sales Order # : 6449806
PWCS PO #: 4504977282
From: SARAH CONKLIN

Ref/WO#:
Core Disposition

PWCS JR3-0105-E (2014-06)

<u>Part Number</u>	<u>Serial No</u>	<u>Qty</u>	<u>Comments/Repair Required</u>	<u>Disposition</u>	<u>Estimate USD</u>
62129-01	15035986	1	REPAIR FINDINGS : PART WAS DEEMED UNSERVICABLE. OPTION 1 : REPLACEMENT \$ 32,156.74 USD NEW UNIT RETURNING IS 62129-03 OR OPTION 2 SCRAP PART FOR \$844.41	HD	\$32,156.74

Subtotal \$32,156.74
Sales Tax \$0.00
Total \$32,156.74

Customer Approval Signature: _____ **Date :** _____

The success of this repair which has been quoted is limited by any hidden characteristics not detectable at detail inspection (eg: any previous rework that may result in insufficient material remaining to continue repair). Part may be declared unrepairable/unserviceable. All costs incurred to the point of being determined "unserviceable" will be charged to the customer. Price indicated is based on the identified work scope. Unforeseen conditions discovered during repair requiring additional work will be immediately communicated to the customer with revised pricing. The part turn time may be affected.



Repair Estimate

Sold To: 77560
Galaxy Aerospace (M) Sdn Bhd
Customer PO # : PO-24-8075

Date: 2024.09.10
SAP Repair Sales Order # : 6449860
PWCS PO #: 4504977291
From: SARAH CONKLIN

Ref/WO#:
Core Disposition

PWCS JR3-0105-E (2014-06)

<u>Part Number</u>	<u>Serial No</u>	<u>Qty</u>	<u>Comments/Repair Required</u>	<u>Disposition</u>	<u>Estimate USD</u>
62129-03	17056303	1	REPAIR FINDINGS: PART WAS FOUND UNSERVICEABLE OPTION 1 REPLACEMENT NEW UNIT 62129-03 : \$32,156.74 OPTION 2 SCRAP \$844.41	HD	\$32,156.74

Subtotal \$32,156.74

Sales Tax \$0.00

Total \$32,156.74

Customer Approval Signature: _____ **Date :** _____

The success of this repair which has been quoted is limited by any hidden characteristics not detectable at detail inspection (eg: any previous rework that may result in insufficient material remaining to continue repair). Part may be declared unrepairable/unserviceable. All costs incurred to the point of being determined "unserviceable" will be charged to the customer. Price indicated is based on the identified work scope. Unforeseen conditions discovered during repair requiring additional work will be immediately communicated to the customer with revised pricing. The part turn time may be affected.