



# CHOPPERTECH SERVICES SDN BHD (1161592-X)

No.38 & 38-1, JALAN TPS 1/7  
TMN PELANGI SEMENYIH  
43500 SEMENYIH, SELANGOR  
MALAYSIA.  
TEL: +6016-8402775.  
FAX NO. +603-21784881

## QUOTATION

Quotation ref.no.:	QUO/CTS/AERO/2021/029	Date:	16 Apr 2021
Your order ref.no.:	9 Apr 2021	CTS GST Number	000068694016

<b><u>BILL TO:-</u></b> <b>Galaxy Aerospace (M) Sdn. Bhd.</b> Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	<b><u>CONTACT:-</u></b> Attn.:Sumaili
---	--

Item	Part Number	Description	Unit Price	Qty	Price	Lead Time
1.	EC-14000-10	Control Box Repair	RM81,300.00	1	RM81,300.00	3-5 Months
<b>TOTAL</b>					<b>RM81,300.00</b>	

Note:

1. Payment :Full payment required.
2. Quote Validity : 30 Days/price might change depend on currency rate or condition of the unit/stock availability.
3. Insurance coverage: Client is required to inform the amount of items that they wish to insure. Without any confirmation from client, our company will automatically insure the items based on the items repair value. If client wish to insure more than the items repair value, client would need to bear the extra insurance cost.
4. Sales Condition : In case of rejection of final repair quotation, **TT&E Fee** will be charged per unit and will be returned as **disassembled condition**. TT&E Fee will become void once repair estimate is provided and approved. A final repair quotation will be submitted to customer's consideration for approval after TDI. For exchange unit, client core unit required to be return to us in 2 weeks time, exchange price might change depend on client core unit condition and OEM justification. (OEM Term & Condition apply)
5. Quoted price are exclude SST and import tax, client need to bear if any SST and import tax that impose by custom.

**FOR: CHOPPERTECH SERVICES SDN. BHD.**

**Mr. Robin Chin**

**Managing Director**

*E-MAIL: rbnchinyt@gmail.com*

*Tel: +6016-8402775*