



CHOPPERTECH SERVICES SDN BHD (1161592-X)

No.38 & 38-1, JALAN TPS 1/7
TMN PELANGI SEMENYIH
43500 SEMENYIH, SELANGOR
MALAYSIA.
TEL: +6016-8402775.
FAX NO. +603-21784881

QUOTATION

Quotation ref.no.:	QUO/CTS/AERO/2021/103	Date:	13 Dec 2021
Your order ref.no.:	RFQ 13 Dec 2021	CTS GST Number	000068694016

BILL TO:- Galaxy Aerospace (M) Sdn. Bhd. Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	CONTACT:- Attn.: Sumaili & Sysamim
--	--

Item	Part Number	Description	Unit Price (RM)	Qty	Price (RM)	Lead Time
1.	10406-20600-1	Control Electric Unit SN1003	49,590.00	1	49,590.00	3-6 Months
2.	261-0396-001	Radar Display Unit SN101 Test and Evaluation & Repair	103,145.58	1	103,145.58	3-5 Months
3.	524-062	Starter Gen SN746 Standard OVH	22,482.00	1	22,482.00	2-3 Months
4.	81440-12-241P	GPS Receiver software upgrade to Q version (Excluded Repair)	25,827.80	1	25,827.80	2-3 Months

Note:

1. Payment : Full payment upon PO issued after TDI.
2. Quote Validity : 30 Days, price might change depend on currency, stock availability, final freight charges and taxes.
3. Insurance coverage: Client is required to inform the amount of items that they wish to insure. Without any confirmation from client, our company will automatically insure the items based on the items repair value. If client wish to insure more than the items repair value, client would need to bear the extra insurance cost.
4. Sales Condition : In case of rejection of final repair quotation, **TT&E Fee** will be charged per unit and will be returned as **disassembled condition**. TT&E Fee will become void once repair estimate is provided and approved. A final repair quotation will be submitted to customer's consideration for approval after TDI. For exchange unit, client core unit required to be return to us in 2 weeks time, exchange price might change depend on client core unit condition and OEM justification. (OEM Term & Condition apply)
5. Warranty: 6 months (Term & conditions apply).
6. Delivery Lead time: Delivery lead time will be influence by parts availability and export license application from original supply country.
7. Tax: Import tax and SST are excluded, if any tax involves during custom clearance process, client required to bear the tax amount.

FOR: CHOPPERTECH SERVICES SDN. BHD.
Mr. Robin Chin
Managing Director
E-MAIL: rbcchinyt@gmail.com
Tel: +6016-8402775