

SAFER CARD

Name: Harry Joinin

Report No.: GAM-ENG/SC/21/0046

Location: Kota Kinabalu

Date: 6 Dec 2021

Report Type:

NCR		Personal (PPE)
	✓	Improper Used
		Location
		Tools
	✓	Procedures
	✓	Not Comply
		Tools Equipment
	✓	Equipment
		Dropped Object
		Stored Energy
		Hygiene
		Hazard
	✓	Electrical
	✓	Work Environmental
✓	Others (Specify)	

Remarks for specify:

GAM PGU KK Store/ Holding room temperature and humidity are out of permissible limit

Brief Description:

GAM PGU KK Store/ Holding room temperature and humidity are out of permissible limit due to 2 X Aircond Unit U/S. EC have been informed for the aircond replacement requirement however EC suggested for repair instead. Repair is not an option since contractor/vendor/supplier unable to get spares for the repair

Improvement / Suggestion:

Replacement of both aircond as soon as possible. Kindly refer to aircond spec and

SAFER CARD

quotation attached. However the quantity of required aircond unit have now become 2 instead of 1 initially

Process:

	HOD
	SM
	FILE

SMS Dept. Remarks:

SMS Updated Dept. Remarks: