

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> ALL ENGINEERING & CAMO DEPARTMENT	<b>FROM:</b> CAMM
<b>CC:</b> QUALITY ASSURANCE DEPARTMENT	<b>DATE:</b> 05 NOVEMBER 2019
<b>REFERENCE NO.:</b> CAMO/MEMO/2019/41	

Dear all,

Please be informed that the following publication has been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement.

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	LEONARDO	TMI 139-509, NEW ISSUE	07.10.2019	AW139 Helicopters that install KIT P/N 3G9560F00212	Viewing window - Replacement (remove and install a new item)	<a href="#">1</a>
2.	LEONARDO	MRBR, ISSUE L	06.2019	AW189	LEONARDO MAINTENANCE REVIEW BOARD REPORT	<a href="#">2</a>
3.	LEONARDO	TMI 139-463, REV B	01.10.2019	AW139 S/N 31051, 31468, and 41007	Nose Landing Gear Support Struts Bracket Bearing - Replacement	<a href="#">3</a>
4.	LEONARDO	TMI 139-510, NEW ISSUE	24.10.2019	AW139 S/N 31499	Undressing procedure – Power supply P/N 071-01041-0001	<a href="#">4</a>
5.	LEONARDO	TMI 139-486, REV. A	25.10.2019	All AW139 Helicopters	Strobe light cover - Replacement procedure (remove and install a new item)	<a href="#">5</a>

Thank You.



**ZATY NADHIRA BINTI MOHAMED ZUHARI**  
**CONTINUING AIRWORTHINESS MANAGEMENT MANAGER**  
**GALAXY AEROSPACE (M) SDN. BHD.**