

## CONTINUING AIRWORTHINESS MANAGEMENT ORGANISATION MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 21.10.2022
<b>REFERENCE NO.:</b> CAMO/MEMO/2022/76	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	LEONARDO	ISSUE 2 REV. 28 TEMPORARY REVISION 2-3	20.10.2022	AW139	AW139 ROTORCRAFT FLIGHT MANUALS SECTION 2 - NORMAL PROCEDURES DOC REF. NO.: 139G0290X002	<a href="#">1A</a> <a href="#">1B</a>
2.	AIRBUS	IN NO. 3811-I-63 REVISION 0	11.10.2022	EC155B	MAIN ROTOR DRIVE - NEW TOOL REFERENCE FOR DAUPHIN MGB OIL FILTER COVER	<a href="#">2</a>
3.	SAFRAN	GSL 3053/20 VERSION B	19.10.2022	SAFRAN ENGINE	ARRIUS 2, ARRIEL 2, ARRIEL 2+ - SHORTAGE - RISK MITIGATION PLAN FOR DRAIN VALVE ASSEMBLY P/N 0292687250	<a href="#">3</a>

**For item no. 1, kindly discard the pdf file that already downloaded and replace it with the new file provided with the GD link given.**

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*

*Harlina*

NUR HARLINA BINTI ABDULLAH  
**TECHNICAL PUBLICATION,  
CAMO DEPARTMENT,  
GALAXY AEROSPACE (M) SDN. BHD**