

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: GAM AMO Dept, GAM CAMO Dept.	FROM: Technical Publication
CC: GAM AM, GAM QAM	DATE: 16.11.2023
REFERENCE NO.: CAMO/MEMO/2023/75	

Dear all,
Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer to all publications below for your acknowledgement and to take action.

NO	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	TEXTRON	REVISION D5	15.09.2023	B300	STRUCTURAL INSPECTION AND REPAIR MANUAL PART NO. P/N 98-39006	1
2	TEXTRON	REVISION B4	15.09.2023	B300	STANDARD PRACTICES MANUAL PART NO. 130-590031-487	2
3	HARTZELL	MANUAL NO. 202A REV. 54	NOVEMBER 2023	HC-B4MP-3C	STANDARD PRACTICES MANUAL (VOLUME 7) CONSUMABLE MATERIALS PACKAGING AND STORAGE	3
4	TEXTRON	MTL-55-02 REV. 1	14.11.2023	B300	SERVICE LETTER STABILIZERS - HORIZONTAL FASTENER REPLACEMENT	4
5	AIRBUS	SIN NO. 3951-S-00 REVISION 0	15.11.2023	GENERAL	SAFETY INFORMATION NOTICE GENERAL - COCKPIT / CABIN PASSENGER SAFETY BRIEF & OPERATOR / CREW / PILOT SAFETY RISK ASSESSMENT	5
6	PRATT AND WHITNEY CANADA	REV. 32.0	06.11.2023	AW139	PT6C-67C MAINTENANCE MANUAL MANUAL PART NO.: 3045332	6
7	SAFRAN	GSL NO. 3109/23 VERSION A	10.11.2023	GENERAL	GENERAL SERVICE LETTER ALL ENGINES - LIFE-LIMITED PART - RETURN TO AN APPROVED REPAIR CENTER IN CASE OF END OF SERVICE LIFE	7

8	LYCOMING	SL NO. L293 NEW ISSUE	09.11.2023	R44	SERVICE LETTER AIR TEMPERATURE SENSOR P/N 60C28409	8
9	ROBINSON	REV NOV 2023	NOVEMBER 2023	R66	R66 MAINTENANCE MANUAL AND ICA DOC REF: RTR 660 VOLUME I	9
10	AIRBUS	IN NO. 3964-I-00 REVISION 0	13.11.2023	EC120B	AIRBUS HELICOPTER - EC120B INFORMATION NOTICE TECH DATA: UPCOMING REVISION OF THE H120/EC120 PUBLICATIONS	10
11	TEXTRON	MC KA-2001-04 REV 1	NOVEMBER 2023	B300	MULTI-ENGINE TURBOPROP COMMUNIQUE ATA 00- IMPORTING AND EXPORTING AIRCRAFT - CHANGED COMPANY NAME ATA 22- ARTICLE DELETED ATA 27-UNIVERSAL TRAVEL BOARD-ADDED FIGURE TO CLARIFY PROCEDURE ATA 32-HYDRAULIC POWER-PACK PARTS BREAKDOWN-PART NAME CHANGE FROM SCREEN TO FILTER ATA 32- FOOT AND MOUTH DISEASE, WHEELS AND BRAKES-REMOVED, INFORMATION NO LONGER RELEVANT ATA 33-WINGTIP NAVLIGHT LENSE INSTALLATION-UPDATED RESIN AND HARDENER PART NUMBER ATA 33- ROTATING BEACON REPLACEMENT- REMOVED,INFORMATION NO LONGER RELEVANT ATA 77- ITT HARNESS- ADDED PART NUMBER OF GROMMET	11

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!



DEANNA IZZATY BINTI AHMAD SHOUFIK
TECHNICAL PUBLICATION,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD.