

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO TO: GAM AMO Dept, GAM CAMO Dept. FROM: Technical Publication CC: GAM AM, GAM QAM DATE: 08.08.2024 REFERENCE NO.: CAMO/MEMO/2024/84

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer to all publications below for your acknowledgement and to take action.

| NO. | VENDOR | REV. NO. | ISSUE/REV DATE | EFFECTIVITY | SUBJECT | LINK TO GAM SERVER |
|-----|---------------------|-------------------------------|-------------------|-------------------------------------|--|--------------------------|
| 1. | LEONARDO | TMI109-544 NEW ISSUE | 05.08.2024 | A109E | TAIL ROTOR ROTATING CONTROLS HALF-SCISSORS REMOVE AND INSTALL PROCEDURE | 1 |
| 2. | MYSAFT BATTERIES | SIL NO: SIL 0124 REV 1 | 02.08.2024 | ALL MYSAFT BATTERIES PRODUCTS | REGULAR CHECK AND OVERHAUL FLOW DIAGRAM CORRECTION | 2 |
| 3. | GOODRICH | SIL NO.: SIL-2014-01 REV 5 | 28.04.2023 | ALL GOODRICH PRODUCTS | EQUIPMENT/FURNISHINGS - LOAD CHECK TOOL USAGE | <u>3</u> |

Please be advise, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!

DEANNA IZZATY BINTI AHMAD SHOUFIK TECHNICAL PUBLICATION, CAMO DEPARTMENT, GALAXY AEROSPACE (M) SDN. BHD.