

	Continuing Airworthiness Notice (CAN)	
	CAN No. / Rev No.	CAN 03 / R0
	Date	17-Sep-2020

To : GAM AMO Engineering Manager
CC : GAM Accountability Manager, GAM Quality Assurance Manager
From : Continuing Airworthiness Management (CAM) Manager
Subject : Worksheet Reference for B300 General Maintenance Task

1. REFERENCE

- a. Super King Air B300/B300C Maintenance Manual 130-590031-11 latest approved revision
- b. King Air Chapter 20 Standard Practice – Airframe 130-590031-487 latest approved revision

2. APPLICABILITY

- a. RMPAOF's B300 fleet maintained by GAM AMO

3. INTRODUCTION

- a. A document review by the Airworthiness Review Staff (ARS) had found that some worksheet reference to the Illustrated Parts Catalog (IPC) to perform the maintenance task.
- b. This maintenance task are usually simple and general maintenance tasks that the procedure is not available in the Maintenance Manual (MM). OEM had been contacted and clarifies that to refer to ATA 20 Standard Practices for procedure that are not in the MM. Refer Appendix 1.

4. REQUIREMENT

- a) For maintenance procedure not available in the MM, LAE shall refer to ATA 20 Standard Practice in accomplishment of the task.
- b) All worksheet shall state the reference as per para. 1 (b) instead of referring to the IPC.

Kindly be informed and adhered to the requirement.



Zaty Nadhira Binti Mohamed Zuhari
 CAM Manager
zaty@galaxyaerospace.my

 Galaxy Aerospace <small>maintenance . repair . overhaul</small>	Continuing Airworthiness Notice (CAN)	
	CAN No. / Rev No.	CAN 03 / R0
	Date	17-Sep-2020

APPENDIX 1



**Enquiry on General Task not available in Maintenance Manual
(CID:9kx3wrrfhhhh\$j8qgf)**

From: TeamTurboprop Support <TeamTurboprop@txtav.com>
Subject: RE: Enquiry on General Task not available in Maintenance Manual
 (CID:9kx3wrrfhhhh\$j8qgf)
Date: 4 August 2020 at 9:32:42 PM MYT
To: Amirah Fatini Zainal <fatini@galaxy aerospace.my>
Cc: "Wimberly, Hallie" <HWimberly@txtav.com>, "Ealey, Cindy" <CEaley@txtav.com>, Ezhan Izzad Mohd Nor <ezhan.galaxy@gmail.com>

If the process is not in the AMM, then best shop practices, AC43.13 and ATA 20 Standard practices will be used when needed.

Regards,

Turboprop Technical Support Team
 Textron Aviation

-----Original Message-----

From: TMDC [mailto:TMDC@txtav.com]
Sent: Tuesday, August 4, 2020 8:26:29 AM
To: Amirah Fatini Zainal, TeamTurboprop Support
Cc: Wimberly, Hallie, Ealey, Cindy, Ezhan Izzad Mohd Nor
Subject: Enquiry on General Task not available in Maintenance Manual

Technical Support, Can you please assist and reply to customer?

Thank you.  Please consider the environment before printing this document.
 Hours: Monday thru Friday, 8:00am to 4:30pm Central Time. Prices are valid for 30 days.

Personal upcoming out of office dates:
 Aug 11

Please contact TMDC in my absence.

TMDC@txtav.com
<http://pubs.txtav.com>

Sarah Ball
 Aftermarket Support Specialist Sr., Technical Manual Distribution Center for Beechcraft and Hawker Technical Publications
 Textron Aviation
 1.800.796.2865 PHONE
 +1.316.517.6215 PHONE
 +1.316.671.2540 FAX

Beechcraft



Hawker

TEXTRON AVIATION