

To: All Engineering Staffs, CAMO Staffs & Operators.

From: CAMO

CC: Quality Assurance Staffs

Issue: 17 June 2019

Subject: TMI 189-039 - Generator exhaust hoses (Number 1 engine access door) – Replacement procedure

---

Dear All,

Temporary maintenance instruction for AW189 has been published through Leonardo Portal. Kindly refer TMI 189-039 for your acknowledgement.

Thank You.



Shamsul Kamar Bin Samsudin

Acting Continuing Airworthiness Manager

17 June 2019