

To: All Engineering Department, CAMO Department & Operators.

From: CAMO

CC: Quality Assurance Department

Issue: 17 June 2019

Subject: TMI 139-475 Rev. A - Engine LH/RH Reinforcement P/N 3P5333A15352 / 3P5333A15452
Replacement Procedure

Dear All,

Temporary maintenance instruction for AW139 has been published through Leonardo Portal. Kindly refer TMI 139-475 revision A for your acknowledgement. For your information, this TMI not applicable for our aircraft serial number.

Thank You.



Shamsul Kamar Bin Samsudin

Acting Continuing Airworthiness Manager

17 June 2019