GalaxyAerospace	※
maintenance renair overhaul	

Galaxy Aerospace (M) Sdn. Bhd, (1040262-D) No 79-1, 1st floor, Jln PJU 1A/41B, 47301 Petaling

GALAXY-HSE-SMS Document No.: 08 MAY 2018 Release date:

	mainten	ance.repair.overhaul	Jaya, Selang	or Darul Ehsan, Ma	aysia.		HIRAF	RC R	EGISTER	Release date:		
LUDADO NO		CANA (CANA (IV. 24/40)		B	08 MAY 2018				Nizam (SM)	SMS Page:	Mohammad Nizam Jaafar	
				Date conducted:		Conducted by:				Approved by:	Winn	
Pro	ocess/ Location:	New CAMO capability (EC 155 B1)		Revision:	0	Received By:		Salman (QAM)	Signature:			
No.			entification			Likeli-	Ris	k Asse	Existing Risk Control (if	Recommended and	Risk Contro	
		Workplace/ Activity	l	Hazard	Consequences/ Effects	hood	Severity	Rating	any)	additional Control	PIC	Status/ Remarks
1	Insert picture here	To add EC 155 B1 AW189 in CAMO capability list, to obtain CAAM Approval to manage the continuing Airworthiness of Sultan Pahang helicopter	upgraded interest of with non-c	n of capability will implicate f the company ompliance with ty regulation	The company can't achieve their business opportunities and commercial values	4	D	4D	Admin. Control: Refer to SMS Manual Part 14.2 (Process of management of change MOC)	Admin. Control: Identify gaps and weaknesses to ensure the achievement	QAM	Risk reduced to 2D after additional control measure and found on acceptable level
2	Insert picture here	Appointed ARS personal have to be assessed by authority for additional competencies to issue authorisation by CAMO and QA	the comp	eate interest of any with non- with authority sulation	Nominated ARS can only be issue authorization when accepted and approved by authority	3	Е	3 E	Admin. Control: Refer to AN 6102 Para 10.2	Admin. Control: Identify gaps and weaknesses to ensure the achievement	CAM	Risk reduced to 1E after an additional control measure and found was on acceptable level
3	Insert picture here	An appropriate training have to attend by CAMO staff	perform function d adequate	n of ability to a prescribed lue to lack and training as per quired	Difficulty to perform a task as per job assigned	2	Е	2E	Admin. Control: Refer to MOE Part 3.4.5 (Training and continuation training)	Admin. Control: Relevant training required: #EC155 B1 Gen fam #CAME	۵	Risk reduced to 1E after an additional control measure and found on acceptable level
4	Insert picture here	Required a work station for maintenance planning and storage area and locker for aircraft record	facilities v unsaf environmer affe	or poor storage will expose to e working nt which lead to cted the mentation	The unsafe or improper storage of aircraft documentation which lead to environmental deterioration and theft	4	D	4D	Admin. Control: Refer to MOE Part 2.14.2 (Technical record control)	Admin. Control: Identify gaps and weaknesses to ensure the documentation is well kept	SM	Risk reduced to 2D after additional control measure and found on acceptable level