

LIDADC DECICTED

GALAXY-HSE-SMS Document No.: 22 Oct 2018 Release date:

	maintenance . repair . overhaul Jaya, Selangor Darul Ehsan, Malaysia.					HIRARC REGISTER				SMS Page:	APPENDIX C	
HIRA	RC NO.:	GAM/SMS/H-51(18)		Date conducted:	22 Oct 2018	Conducted by:			Nizam (SM)	Approved by:	Mohammad Nizam Jaafar	
Pro	cess/ Location:	Additional line & base main't facility (PGU)		Revision:	0	Received By:			Salman (QAM)	Signature:	Dign	
		Hazard Identification				Risk Asses			ssment	Risk Control		ol
No.		Workplace/ Activity		Hazard	Consequences/ Effects	Likeli- hood Severity Risk Rating		Existing Risk Control (if any)	Recommended and additional Control	PIC	Status/ Remarks	
1	Insert picture here	GAM to certified additional maintenance facilities for their operation at line & base maintenance at PGU Subang facility as per AMO Part 145 requirement.	upgraded interest of with non-co	n of capability will implicate f the company ompliance with ty regulation	The company can't achieve their business opportunities and commercial values	4	E	4 E	Admin. Control: Refer to SMS Manual Part 14.2 (Process of management of change MOC)	Admin. Control: Introduce a MOC checklist to Identify gaps and weaknesses	QAM	Risk reduced to 3E after existing and additional control measure and find on acceptable level
2	Insert picture here	PGU Subang maintenance facilities have a dedicated maintenance area include shelter, hangar space, store and maintenance office.	authority s Part 14 requiremer be unsa	es not meet the standard as per 45 & safety nt which lead to afe working conment.	Improper maint. facilities may harm personnel, aircraft and a/c component damage	3	С	3 C	Admin. Control: Refer to SMS Manual Part 13.2 (Safety Audits) and MOE Part 3.1.2	Admin. Control: To do an observation and surveillance for identify of areas for improvement	QAM SM	Risk reduced to 2C after existing and additional control measure and find on acceptable level after review
3	Insert picture here	Requirement of test equipment, standard tools, calibrated tools, special tools and GSE and Maintenance platform for the maintenance operation	meet the authority which lead	oment do not e standard of y compliance to be an unsafe environment	Equipment that didn't meet the specifications can cause of a/c and component damage	4	С	4C	Admin. Control: Refer to MOE Part 2.4 (Acceptance of tool and equipment)	Admin. Control: To observe for identification and the COC of equipment for a save utilization	QAM EM SM	Risk reduced to 2C after existing and additional control measure and find on acceptable level after review
4	Insert picture here	Appropriate training and qualified authorized personnel for task to attend an approve type course and others appropriate related training	perform function a lack and ad	n of ability to a a prescribe nd task due to equate training r required	Difficulty to perform a task as per task assigned and will implicated to a/c safety	3	В	3B	Admin. Control: Refer to MOE Part 3.4.5 (Training and continuation training)	Admin. Control: An additional related training to enhance personal capabilities as required	QAM EM SM	Risk reduced to 1B after additional control measure and find on acceptable level after review



No 79-1, 1st floor, Jln PJU 1A/41B, 47301 Petaling Jaya, Selangor Darul Ehsan, Malaysia.

HIRARC REGISTER

GALAXY-HSE-SMS Document No.: 11 Sept 2017 Release date: SMS Page: APPENDIX C Mohammad Nizam Jaafar

								_	SMS Page:	APPENDIX C	
HIRARC NO.:		Continuation of GAM/SMS/H-	13(17) Date conducted:	11 Sept 2017	Conducted by:			Nizam (SM)	Approved by:	Mohammad Nizam Jaafar	
Process/ Location:		Additional line & base maintenan	0	ı	Received By: Salman (QAM)			Signature:	Diyu		
		Hazard Identification				Ris	k Asses	sment	Risk Control		
No.		Workplace/ Activity	Hazard	Consequences/ Effects	Likeli- hood	Severity	Risk Rating	Existing Risk Control (if any)	Recommended and additional Control	PIC	Status/ Remarks
5	Insert picture here	Chemical and compressed gas cylinder handling and storage, POL storage management and waste management	Uncontrolled condition which lead to unsafe condition for example chemical spillage, chemical reaction and leaking of inert gases	Contributing to industrial fire which affected aircraft and personnel safety	4	В	4B	Admin. Control: Refer to Safety Bulletin, Issue June 2017 (Storage and handling chem.)	Admin. Control: To established required procedure and related training	EM	Risk reduced to 2D after existing and additional control measure and find on acceptable level
6	Insert picture here	GAM - MIAT Subang maintenance facilities evacuation and salvage operation in hangar and office	maintenance facilities lead to unsafe act for example the action and		4	В	4B	Admin. Control: Refer to SMS Manual Part 15 (Emergency response plan)	Admin. Control: To customize ERP layout plan at GAM-MIAT facilities as per requirement		Risk reduced to 2D after existing and additional control measure and find on acceptable level
7	Insert picture here	Galaxy Aerospace scrapped material management and control requirement	Uncontrolled scrap material which lead to unsafe condition	Unserviceable or scrap item, spares and component are potentially to be accidently reused	3	В	3B	Admin. Control: Refer to Safety Bulletin, Issue August 2017 (Safety in aviation industries)	Admin. Control: To established procedure for the required condition		Risk reduced to 3E after existing and additional control measure and find on acceptable level
8	Insert picture here	GAM - MIAT Subang facilities aircraft maintenance area (hangar), store and office area prohibition control (visitor, contractor staff or student) requirement	Unsafe condition which lead to unsafe act for example visitor or student did an unforeseen dangerous attempt on the aircraft	damage and	4	В	4B	Admin. Control: Refer to Safety Memo, ref no: GAM- S/ME/05/OCT16 Facility Access Policy	Admin. Control: To established procedure for the required condition	٠	Risk reduced to 2E after existing and additional control measure and find on acceptable level