Gi	alaxyAerospace	※
	naintenance renair averbaul	

Galaxy Aerospace (M) Sdn. Bhd, (1040262-D) No 79-1, 1st floor, Jln PJU 1A/41B, 47301 Petaling

GALAXY-HSE-SMS Document No.: 05 Nov. 2018 Release date:

maintenance.repair.overhaul Jaya, Selangor Darul Ehsan, Malaysia.			HIRARC REGISTER				SMS Page:	APPENDIX C				
HIRA	HIRARC NO.: GAM/SMS/H-53(18)		Date	te conducted:	01 Nov. 2018	Conducted by:			Nizam (SM)	Approved by:	Mohammad Nizam Jaafar	
Pro	Process/ Location: New GAM HQ for Galaxy Aerospace		ice operation Rev	vision:	0	Received By:		Salman (QAM)	Signature:	Dign		
		Hazard Id	entification			Risk Assessment					Risk Control	
No.		Workplace/ Activity	Hazaı	rd	Consequences/ Effects	Likeli- hood	Severity	Risk Rating	Existing Risk Control (if any)	Recommended and additional Control	PIC	Status/ Remarks
1	Insert picture here	Justification for changes is to centralized all technical and operational for a better communication and coordination without any disruption to regulation	Transition of operation loo implicate inte company w compliance wi regula	cation will erest of the vith non- ith authority	The company can't achieve their business opportunities and its commercial values	4	E	4 E	Admin. Control: Refer to SMS Manual Part 14.2 (Process of management of change MOC)	Admin. Control: Introduce a MOC checklist to Identify gaps and weaknesses	QAM	Risk reduced to 3E after existing and additional control measure and find on acceptable level
2	Insert picture here	GAM AMO, CAMO, DOA and other department will be operate at new GAM HQ at Helicopter Centre Subang due to enhance and expand their operation	The facilities n standard as authority requi lack of fire pre protection sy evacuatio	s per local irement with evention and ystem and	Improper of the facilities may harm personnel, property and a/c component due to industrial fires	4	С	4C	Admin. Control: Refer to SMS Manual Part 15 (Emergency response plan)	Admin. Control: To carried out an observation and surveillance for identify of areas for improvement	QAM SM	Risk reduced to 2C after additional control measure and find on acceptable level after review
3	Insert picture here	Transition and expansion of office facilities with include Admin, AMO, CAMO, DOA, QA, SMS and other related department at the new HQ that accommodate at level 1	The facilities n authority stan Part 145, Part I safety require lead to be uns condit	ndard as per M, Part 21 & ment which safe working	Improper of the facilities may harm personnel, property and damaged to a/c component	4	С	4C	Admin. Control: Refer to SMS Manual Part 13.2 (Safety Audits) and MOE Part 3.1 (QA Audit)	Admin. Control: To carried out an observation and surveillance for identify of areas for improvement	QAM EM SM	Risk reduced to 4C after additional control measure and find on acceptable level after review
4	Insert picture here	Transition of workshop facilities with include Battery shop (LA & NiCad), Emergency Equipment shop, Avionics shop and mechanical shop at the new HQ	requirement w	ndard as per nd safety which lead to working	Which lead to aircraft or aircraft component damage and affecting aircraft safety	5	D	5D	Admin. Control: Refer to SMS Manual Part 13.2 (Safety Audits) and MOE Part 3.1 (QA Audit)	Admin. Control: To carried out risk assessment on the related areas to enhance safety	QAM EM SM	Risk reduced to 3D after additional control measure and find on acceptable level after review



Galaxy Aerospace (M) Sdn. Bhd, (1040262-D)
No 79-1, 1st floor, Jln PJU 1A/41B, 47301 Petaling
Jaya, Selangor Darul Ehsan, Malaysia.

HIRARC REGISTER

Document No.: GALAXY-HSE-SMS

Release date:

SMS Page: APPENDIX C

HIRA	RC NO.:	Continuation of GAM/SMS/H-	Date conducted:		С	onducted b	y:	Nizam (SM)	Approved by:	Mohamm	ad Nizam Jaafar
Process/ Location: New GAM HQ for Galaxy Aerospace operation Revision:			Received By:			Salman (QAM)	Signature:		<u>_</u>		
		Hazard Identification			Risk Assess					Risk Contro	ol
No.	Workplace/ Activity		Hazard	Consequences/ Effects	Likeli- hood	Severity	Risk Rating	Existing Risk Control (if any)	Recommended and additional Control	PIC	Status/ Remarks
5	Insert picture here	Transition of store facilities with include Bonded store, POL store, Quarantine are, Rubberize item store ESD equipment and receiving area at the new HQ	The facilities not meet the authority standard as per Part 145 and safety requirement which lead to be unsafe working condition	Which lead to aircraft or aircraft component damage and affecting aircraft safety	5	D	5D	Admin. Control: Refer to SMS Manual Part 13.2 (Safety Audits) and MOE Part 3.1 (QA Audit)	Admin. Control: To carried out risk assessment on the related areas to enhance safety	EM SM	Risk reduced to 3D after additional control measure and find on acceptable level after review
6	Insert picture here	Transition of logistic facilities with include receiving area, acceptance procedures, parts segregation, FIFO procedure implementation, incoming and outgoing procedure at new HQ	authority standard as per Part 145 and safety	Which lead to aircraft or aircraft component damage and affecting aircraft safety	5	D	5D	Admin. Control: Refer to SMS Manual Part 13.2 (Safety Audits) and MOE Part 3.1 (QA Audit)	on the related	EM SM	Risk reduced to 3D after additional control measure and find on acceptable level after review
7	Insert picture here	Transition of facilities with include Galaxy Aerospace scrapped material procedure management and waste control management	Uncontrolled scrap material and poor waste management which lead to unsafe working environment	Scrap item will potentially to be accidently reused and waste will affects the presence of FOD	4	С	4C	Admin. Control: Refer to SMS Manual Part 13.2 (Safety Audits) and MOE Part 3.1 (QA Audit)	Admin. Control: To established procedure for the required condition and requirement	EM	Risk reduced to 2C after additional control measure and find on acceptable level after review
8	Insert picture here	Transition of new facilities with effected the security of facilities, property, spares, equipment, tools and component.	A poor preparedness of security supervision, alertness and monitoring with lead to unsafe working environment	Potential loss of property as a result of being stolen, robbed treacherous and sabotage	4	С	4C	Admin. Control: Refer to SMS Manual Part 13.2 (Safety Audits) and MOE Part 3.1 (QA Audit)	Eng. Control:	HR IT	Risk reduced to 2C after additional control measure and find on acceptable level after review