

GALAXY AFROSPACF (M) SDN. BHD. [1040262-D] Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia

International Aerospace Centre, SAAS Airport,

Subang Malaysia

Attention: Mr. Syafrul Yamani

Engineering Manager

syafrul@galaxyaerospace.my

Work Order Number:

2022-11574

Work Pack Reference:

9M-BOF-11574

Date Issued:

17/06/2022

A/C Registration / SN:

1

9M-BOF/49053

Sheet:

1 of

Description:

Item

Description/Task/Inspection

62-01 CHECK POST INSTALLATION OF MR HUB

RETAINING ASSEMBLY BOLTS. (5 FH - 10 FH)

Reference

AMPI 89-A-05-21-00

Man Hours

(PLEASE ADVISE)

Remark/Notes:

- 1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

Email: zaty@galaxyaerospace.my



GALAXY AFROSPACE (M) SDN_BIID. [1040262-D]
Suite 11-14. Helscopter Centre, Malaysia International Aerospace Centre
Sultan Abru Azr Shah Airport, 47200 Sultana, Selanger Malaysia.
Tel: +803 7734 7226. [1ax. +803 7734 7226]
www.galaxyuerospace.my | enquiry@gulaxyaerospace/my|

WORKPACK

CLIENT/OWNER: FIRE AND RESCUE SERIAL NO. HOURS LDG/CYCLE WORKPACK NO: 9M-BOF-11574 DEPT. OF MALAYSIA 1941 AIRCRAFT 49053 877:30 WORK/INSP/DESC: CAAM FINDING AIRCRAFT TYPE: AW189 951.53 AERONET JOB NO.: 2022-11574 REGISTRATION: 9M-BOF 780225 #1 ENGINE: 877:30 AJL REF NO .: BASE/FACILITY: WMSA 780234 #2 FNGINE SHEET 1 OF 1 DATE IN: 9.5.12 OUT: 9.5.12 NG/N1 NF/N2 Other requirements/information: Raised by and date: Reason for raising: CAAM FINDING RECTIFICATION TO BE CARRIED OUT CAMO G.A: Ihsan Masri NIL 17/06/2022 List of scheduled inspection and all work carried out under this workpack Master Signature Schedule DATE including individual reference INSPECTION COMPLETED INSPECTION / WORK WORKSHEET REF NAME SIGNATURE NO. APP/STAMP 62-01 CHECK POST INSTALLATION OF MR HUB 11574-001 1 RE... 9.5.12 MUHAMAD M010 2HAPIR 8112 PART 145 - AMO RELEASE STATEMENT NAME MUTA MAD THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND SIGN & APPROVAL * OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE *IF DIFFERENT FROM ABOVE, OEM PUBLICATION/REVISION..... FIRM GAM DATE 9.5.12 * TICK WHERE APPLICABLE MUHAMMAD INSAN MASE PART M - CAMO ACCEPTANCE STATEMENT SIGN & APPROVAL DATE CAMO Planner THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION Galaxy Aerospace (M) Sdn. Bho AND UPDATED IN THE MAINTENANCE SOFTWARE. (1040262-D) FORM REF. GAM/C-004 Rev 3 (01/



☐ TICK ✓ WHERE APPLICABLE

GALAXY AFROSPACE (M) SDN BLID [1040262-D]

WORKSHEET

Suite 11-14, Holocopter Centre, Mala, su international Aerospace Centre, Sultan Abdul Aniz Shat, Amport, 47205 Suhang, Selanger, Malaysia Tel. +603 7734 7226 | Lax. +603 7734 7226 | www.gulfan yierospace my | enquir, et galaxyaerospace my CLIENT/OWNER: FIRE AND RESCUE WORKSHEET NO: SERIAL NO. HOURS LDG/CYCLE 11574-001 DEPT. OF MALAYSIA WORK/INSP/DESC: AIRCRAFT 49053 REFER WORKPACK 62-01 CHECK POST AIRCRAFT TYPE: AW189 WORKPACK REF: 9M-BOF-11574 #1 ENGINE: 780225 REFER WORKPACK REGISTRATION: 9M-BOF AJL REF NO .: REFER WORKPACK BASE/FACILITY: WMSA #2 ENGINE: 780234 REFER WORKPACK SHEET DATE IN: REFER WORKPAC NG/N1 NF/N2 OF Reason for raising: CAAM FINDING RECTIFICATION TO BE CARRIED OUT 62-01 CHECK POST INSTALLATION OF MR Raised by and date: Other requirements/information: CAMO G.A; Ihsan Masri HUB RETAINING ASSEMBLY BOLTS. (5 FH - 10 FH) NIL 17/06/2022 Technician Description * Eng. CRS Item Date 62-01 FUNCTIONAL CHECK (TORQUE CHECK) OF THE MAIN ROTOR HUB RETAINING BOLTS 1 PERFORM A TORQUE CHECK OF THE MAIN ROTOR HUB RETAINING ASSEMBLY BOLTS. ONE OFF CHECK AFTER INSTALLATION. NOTE: RE-TORQUE CAN BE APPLIED FOR A MAXIMUM OF 5 TIMES DMC REF: 89-A-62-21-00-00A-340A-A 9.5.12 MRBR REF: GEN62-01 NOTE: TASK IS REFERENCED TO CAAM FINDING ON 9M-BOF-10876 REMARK: RE - TOR QUE CHECK CARPIED HEAD REMOVAL. 91-BOF - 11376 NOTE : FOR MRH REFER TO INSTALL ATON. REFER TO 91-BUF-10876 1.1 THE DUPLICATE INSPECTION FOR TASK 62-01 FUNCTIONAL CHECK (TORQUE CHECK) OF THE MAIN ROTOR HUB RETAINING BOLTS (CORRECT INSTALLATION, PROPER INSTALLATION AND SECURITY OF ATTACHMENT) CARRIED OUT IN ACCORDANCE WITH THE CAD 8601 PARA 5.42(3) M010) 9.5.12 DATE: 1st Inspector Sign: Approval/Stamp DATE: 2nd Inspector Sign Approval/Stamp: *The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service. The work recorded above has been carried out in accordance with the requirements of the for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



GALAXY ALROSPACE (M) SDN. BLID. [1040262-D].
Suite 11-14. Helicopter Centre. Multi-six International Aerospace Centre
Suitan Abrud Aziz Shah Aeront. 472CC Suitang. Setanpor, Mallej Six.
Tid. 46C3.7734.7256. [Tid. 46C3.7734.7556.]
www.gulax.iserospace.mix.; enquiry@galaxyaerospace.my.

PARTS REPORT

CLIENT/OWNER: JABATAN BOMBA DAN SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 11574-001 PENYELAMAT MALAYSIA 49053 REFER WORKPACK AIRCRAFT WORK/INSP/DESC: 62-01 CHECK POST AIRCRAFT TYPE: AW189 780225 REFER WORKPACK 9M-BOF-11574 #1 ENGINE: WORKPACK REF: REGISTRATION: 9M-BOF 780234 REFER WORKPACK BASE/FACILITY: WMSA REFER WORKPACK AJL REF NO .: #2 ENGINE: SHEET: DATE IN: REFER WORKPACK OUT: REFER WORKPACK OF NG / N1 NF/N2 1 REASON FOR RAISING: CAAM FINDING RECTIFICATION TO BE CARRIED OUT 62-01 Raised by and date: CAMO G.A; Ihsan Masri Other requirements/information: CHECK POST INSTALLATION OF MR HUB RETAINING ASSEMBLY BOLTS. (5 FH - 10 NIL FH) 17/06/2022 Serial Number Lifed Item Information Part No Release Description Item Qty Position Reason TSN/TSO/DUE/TIMEX Off On Reference NAME FIRM SIGN & APPROVA DATE GAM MUHAMMO M010 9.5.22 The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service. The work recorded above has been carried out in accordance with the requirements of the for the time being in force and in that respect the aircraft / equipment is considered fit for release to service. TICK WHERE APPLICABLE