

Directorate General Technical Airworthiness d/a PANGKALAN UDARA SUBANG 40000 SHAH ALAM

			* (lick v. oi				
C	ORRECTIVE ACTION REQUEST	Standard PU 2103	*Catego	ry Critical	Majo X Mino		
SECTION	1: DETAILS OF AUDIT						
Auditor	Lt Col Dr. Ismail bin Yusof RMAF			Audit No	65 /	23	
Auditee	Azillah bin Matap	*	Position:	CAR No	6 of	12	
Regulation 5.1.2 - Publications Instructions and Orders and Data.			QM X SMM Others	GMM Galaxy Aerospace (M) Sdn Bhd			
SECTION	2: NON-CONFORMANCE (Include details of objective e	vidence)					
Ref #1. Pl	U 2103 TAMM 2nd Edition, Para 5.1.2, Page R5 -	1 of 16.					
equipmer evidence	MO is obliged to perform maintenance on state on the information accordance with DAR/OEM approved techn of DAR authorization signature on the Airframe informed / knows that, instruction in related SB	ical publication Service Bulle	ons, instruc	tions, orders an Engine Service	nd data. How Bulletin List	ever, no	
Audien			A d : .			·)	
Auditor	Date	9 / 2	Audit	ee			
SECTION	3: ROOT CAUSE AND CORRECTIVE ACTION (Details)	ermination of root	cause and actic	on plan including com	pletion date)		
Root Cau			e complete		1 1 2	3	
Failed	to provide the evidence during audit.						
Corrective	e Action :						
Copy of	f evidence as per attached.						
Auditee	Position:		Da	ate/[/		
SECTION	4: FOLLOW-UP DETAILS AND CLOSE OUT	DON'T STATE					
Verificatio	on of implemented corrective actions:						
Verified	By *CAR Clo	ose Out (Tick	√) Da	ate/[/_		
	Ye	es No					