

Directorate General Technical Airworthiness d/a PANGKALAN UDARA SUBANG 40000 SHAH ALAM

CORRECTIVE ACTION REQUEST		Standard PU 2103			Major X Minor		
SECTION	1: DETAILS OF AUDIT						
Auditor	Maj Iyas Mubarak bin Othman RMAF			Audit No	65]/[23
Auditee	Omar bin Ahmad		*Position :	CAR No	8	of	12
Regulati	on 4.6.1.a . AMO Facilities.		X QM SMM Others	Galaxy Aerospa	ace (M)) Sdn I	Bhd
SECTION	2: NON-CONFORMANCE (Include details of objectiv	ve evidence)			alignet.	0= 2-111	

Ref #1. MMP Galaxy Aerospace (M) Sdn Bhd (GAM), Para 4.6.2a. to f. page 1 of 2.

The audit found that the management of storage activities such as components, POL and GSE at SUKK is not contained in Ref #1 MMP which is contrary to TAMM Regulation 4.6.1.a.

Auditor	Date Auditee			
SECTION 3 : ROOT CAUSE AND CO	RRECTIVE ACTION (Determination of root cause and action pl	an including	completion date)	
Root Cause :	Date to be completed :	20	1 1 2	3
Inadequate storage procedu	re.			
Corrective Action :				
MMD Dort 4 6 2 hoo hoop r	avria a d			

MMP Part 4.6.2 has been revised.

Auditee	Pos it on	Date / / / /
SECTION 4 : FOLLOW-UP	DETAILS AND CLOSE OUT	
Verification of implemente	ed corrective actions :	

Verified By	*CAR Close Out (Tick √)	Date / / /
	Yes No	




4.6.2 **STORAGE FACILITIES (REGULATION 4.6.2)**

- a. GAM's aeronautical warehouse located at GAM HQ facility and the warehouse is managed, controlled and regulated under GAM Part 145 approved organization by CAAM. The warehouse has been dedicated as a common store for both Civil and Stated registered aircraft.
- b. During office hours storage facilities are accessible only to Warehouse Personnel and locked at the other time.
- c. Consist of environmentally controlled bonded store for storing of parts and components, a segregated Quarantine storage and receipt and dispatch area. Storage facilities are maintained in clean, air conditioned and humidity controlled conditioned.
- d. Storage racks are strong enough to hold large components so that components are not distorted during storage.
- e. Wherever practicable, all aeronautical products should remain packaged in protective material and remain inhibited until ready for installation to minimize damage and corrosion during storage.
- f. A POL item storage at the cabin and located outside of GAM HQ Main Office for storage of fuel, grease and lubricants.
- g. All special tools and equipment for aircraft maintenance are located in a dedicated tools store.
- h. Procedures of store procedures and storage of aircraft component are detailed in the EPM 2-01 (Acceptance of Aircraft Components and Materials).
- i. GAM AMO does not hold any spares or aeronautical product in Stesen Udara Kota Kinabalu (SUKK). All spares and aeronautical products were supplied by RMN to carry out maintenance activity.
- j. The Storage facility in SUKK is managed by RMN Skuadron 503. GAM-HQ supplied the spares and aeronautical product directly to RMN Skuadron 503.

DOCUMENT REFERENCE:	GAM/MMP/AW139HOM			DATE:	29 SEP 2023
ISSUE:	1	AMENDMENT:	6	PAGE:	MMP 4.6.2 1 of 2



MAINTENANCE MANAGEMENT PLAN



GAM HQ Warehouse

DOCUMENT REFERENCE:	GAM/MMP/AW139HOM			DATE:	29 SEP 2023
ISSUE:	1	AMENDMENT:	6	PAGE:	MMP 4.6.2 2 of 2