



CLIENT/OWNER: MALAYSIAN MARITIME ENFORCEMENT AGENCY	SERIAL NO. 31315	HOURS 4113.0	LDG/CYCLE 4571	WORKSHEET NO: UW/M72-02/22-045
AIRCRAFT TYPE: AW139	AIRCRAFT			WORK/INSP/DESC: -
REGISTRATION: M72-02	#1 ENGINE: PCE-KB0740	4113.0	N/A N/A	WORKPACK REF: N/A
BASE/FACILITY: APMM,WMSA	#2 ENGINE: PCE-KB0732	4113.0	N/A N/A	AJL REF NO.: 315-02250
DATE IN: 19/12/22 OUT: 19/12/22			NG / N1 NF / N2	SHEET: 1 OF 2

Reason for raising: **TECH LOG DEFECT - FUEL LEAK AT NO. 1 FUEL DRAIN.**

Raised by and date: **YAZHO 19/12/22**

Other requirements/information: **N/A**

Item	Description	Technician	* Eng. CRS	Date										
1.	<p>INSPECTION CARRIED OUT TO NO. 1 ENGINE FUEL LINE AND TUBE FOUND TUBE CONNECTOR LOOSE DUE TO FUEL LEAK AT FUEL DRAIN. TUBE CONNECTOR RETORQUE AND SECURE I.A.W E.M.M 79.20.03</p> <table border="0"> <tr> <td>TORQUE NUT (2)</td> <td><u>TORQUE VALUE</u> 270-300 lbf in</td> <td><u>TORQUE APPLIED</u> 300 lbf in</td> <td></td> <td></td> </tr> <tr> <td><u>TOOL</u> TORQUE WRENCH</td> <td><u>CONTROL NO</u> LTC 05</td> <td><u>DUE DATE</u> 31/05/2023</td> <td></td> <td>19/12/22</td> </tr> </table> <p>SECURE AND LOOSE ARTICLE CHECK CARRIED OUT FOUND SATISFACTORY.</p>	TORQUE NUT (2)	<u>TORQUE VALUE</u> 270-300 lbf in	<u>TORQUE APPLIED</u> 300 lbf in			<u>TOOL</u> TORQUE WRENCH	<u>CONTROL NO</u> LTC 05	<u>DUE DATE</u> 31/05/2023		19/12/22	 	 	19/12/22
TORQUE NUT (2)	<u>TORQUE VALUE</u> 270-300 lbf in	<u>TORQUE APPLIED</u> 300 lbf in												
<u>TOOL</u> TORQUE WRENCH	<u>CONTROL NO</u> LTC 05	<u>DUE DATE</u> 31/05/2023		19/12/22										

- The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual.
- The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual.
- The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual.
- The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenance Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual

The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



CLIENT/OWNER: MALAYSIAN MARITIME ENFORCEMENT AGENCY	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	UW/M72-02/22-095
AIRCRAFT TYPE: AW139	AIRCRAFT	31315	4113-0	4571	WORK/INSP/DESC: INDEPENDENT INSP.
REGISTRATION: M72-02	#1 ENGINE:	PCE-KB0740	4113-0	N/A	N/A
BASE/FACILITY: APMM,WMSA	#2 ENGINE:	PCE-KB0732	4113-0	N/A	N/A
DATE IN: 19/12/22 OUT: 19/12/22				NG / N1	NF / N2
				WORKPACK REF:	N/A
				AJL REF NO.:	315- 02250
				SHEET:	2 OF 2

Reason for raising: TECH LOG DEFECT - FUEL LEAK AT NO. 1 FUEL DRAIN.	Raised by and date: YAZID 19/12/22	Other requirements/information: N/A
--	------------------------------------	-------------------------------------

Item	Description	Technician	* Eng. CRS	Date
1	<p>INDEPENDENT MAINTENANCE INSPECTION CARRIED OUT FOR CORRECT ASSEMBLY, LOCKING AND CORRECT OPERATIONAL IN ACCORDANCE WITH THE REQUIREMENT OF EPM 1-01 ON THE FOLLOWING ITEM:</p> <p>DESCRIPTION: FUEL DRAIN TUBE INSTALLATION</p> <p>REFERENCE: EAG MM CAP 72-20-03 ITEM 18: TO 270-300 lbf in APPLY: 300 lbf in</p> <p>REMARKS: INSPECTION CARRIED OUT FOUND SATISFACTORY</p>			19/12/22

SIGN: 
 LIC/AH NO: 

- The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual.
 - The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual.
 - The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual.
 - The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenance Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual
- The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



CLIENT/OWNER: MALAYSIAN MARITIME ENFORCEMENT AGENCY	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	UW/M72-02/22-095
AIRCRAFT TYPE: AW139	AIRCRAFT: 31315	4113.0	4571	WORK/INSP/DESC:	-
REGISTRATION: M72-02	#1 ENGINE: PCE-KB0740	4113.0	N/A N/A	WORKPACK REF:	N/A
BASE/FACILITY: APMM,WMSA	#2 ENGINE: PCE-KB0732	4113.0	N/A N/A	AJL REF NO:	315- 02250
DATE IN: 19/12/22 OUT: 19/12/22			NG / N1 NF / N2	SHEET:	1 OF 1

REASON FOR RAISING: **TECH LOG DEFECT - FUEL LEAK AT NO.1 FUEL DRAIN**

Raised by and date: **YAZID 19/12/22**

Other requirements/information: **N/A**

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
NIL									

NAME	FIRM	SIGN & APPROVAL	DATE
YAZID	G A M		19/12/22



- The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual.
- The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual.
- The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual.
- The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenance Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual

The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.