IAR-2023/066 NCR 01

Work Sheet No. 9M-BGG-3730-002, 9M-BGG Aircraft Journey Log (AJL) S/N 000062-000071 and Parts Report of Work Sheet No. 9M-BGG-3730-002 were reviewed and found discrepancies. Refer Supporting Document for details of discrepancies.

- (1) Item 146 of Work Sheet No. 9M-BGG-3730-002 was reviewed and found the technician column was entered dash "-" even though the remarks column stated that "Carried out found satisfactory". Refer Appendix 2.
- (2) Aircraft Journey Log (AJL) S/N 000062-000071 were reviewed and found discrepancies in the AJL.

No.	AJL No.	Remarks						
1.	000062	Fuel total left blank						
2.	000063	Acceptable						
3.	000064	Date column left blank, Next calendar inspection was incorrect						
		declared.						
4.	000065	Date column left blank, Next calendar inspection was incorrect						
		declared.						
5.	000066	Next calendar inspection was incorrect declared.						
6.	000067	Next calendar inspection was incorrect declared, Flight time start and						
		shutdown were left blank.						
7.	000068	Acceptable						
8.	000069	Acceptable						
9.	000070	M3 improper correction(no date),						
10.	000071	Flight time shutdown column was left blank, Engine hour in total this						
		page column was left blank, No rectification for item no 2 entry.						

(3) Parts used in Work Sheet No. 9M-BGG-3730-002 was not declared in the Parts Report. Refer Appendix 3.



A	udit Report
Report No.	IAR-2023/066
Area / Scope	GAM-AMO R66
Date of audit	13 Sept 2023

146	ENGINE.
	REFER TO RR300 SERIES OMM. AND APPLICABLE ENGINE COMPONENT MANUFACTURER'S MAINTENANCE PUBLICATIONS FOR SERVICE AND INSPECTION PROCEDURES.
	ADDITIONAL SERVICE AND INSPECTION INTERVALS ARE SPECIFIED IN § 1-90.
	NOTE: FOR ENGINE-RELATED MATTERS, IF THERE IS A CONFLICT BETWEEN THIS MANUAL AND ROLLS-ROYCE INSTRUCTIONS, ROLLS-ROYCE INSTRUCTIONS TAKE PRECEDENCE. NOTIFY RHC OF DISCREPANCY.
	REFERENCE: R66 AMM 5-45
	REMARKS: C/O. SATIC
Z ·Ce	rifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work aircraft / aircraft component is considered ready for release to service.
III 'Cer	rtifies that the work specified above, except as otherwise specified, was carried out in accordance with
and	in respect to that work the aircraft / aircraft component is considered ready for release to service.
TICH	✓ WHERE APPLICABLE

Appendix 2: Item 146 of Work Sheet No. 9M-BGG-3730-002 was reviewed and found the technician column was dash "-" even though the remarks column stated that carried out found satisfactory.



Α	udit Report
Report No.	IAR-2023/066
Area / Scope	GAM-AMO R66
Date of audit	13 Sept 2023

CLIENT/C	CLIENT/OWNER: JAG HELICOPTERS SDN. BHD.		SERIAL NO.		HOURS LDG/CYCLE			WORKSHEET NO: 3730-002		
AIRCRAF REGISTR	TTYPE: R66		#1 ENGINE: #2 ENGINE:	RRE-200732 NIL	REFER WORKPACK			WORK/INSP/DESC: **100 FH / 12 M WORKPACK REF: 9M-BGG-3730		
	CILITY: WMSA				REFER W	VORKPACK		AJL REF NO.:	REFER WORKPACK	
DATE IN:	DATE IN: REFER WORKPACK OUT: REFER WICHIGACK					NG / N1	NF/N2	SHEET: 1	OF 1	
Item	Part No	Des	cription	Off	Serial Numb	On Qty	Position F	Lifed item Informa TSN/TSC/DUE/Ta		
Item	Part No	Des	emption	Off	f	On City	Position F			
						TO THE PROPERTY OF THE PROPERT				
					Production of the second of			40-04-04-04-04-04-04-04-04-04-04-04-04-0	/	
				ANNA TATALOGRAPH CONTRACTOR CONTRACTOR	-	and a second second second				

Appendix 3(a): Parts Report was not declared even though there were parts replacement.

RECEIVE JOB DES A/C TYP	DNENT/PARTS/MATER TO FROM: JAG H CRIPTION: 100 H E: R VG : 9M - BGG	102100	pierz	GalaxyAerospace* DATE: 19-5-2 023 WORKSHEET NO: 9M-899-373					
No	DESCRIPTION	QTY	P/N	S/N	ARC No	COC No	STABEL		
1.	O-RING	ı	MS29513-212	ch ca	365932	_	-		
) .	OIL FILTER MAY		RR 30000278	NJA	365932		-		
						ama America Salmente e de Constitución de Cons			
							The same of the sa		

Appendix 3(b): Parts replacement as declared in Component/Parts/Material List.