

CONTINUING AIRWORTHINESS MANAGEMENT ORGANISATION MINUTES OF MEETING

Meeting Subject:	Meeting No.	GAM/CAMO/21/028
GASSB/CAMO/AMP/EC155B Issue 1,	Date	25 October 2021
Revision 0, Date: 27 October 2021	Time	10:00 am
	Venue	JADE Room

Attendees:

No.	Name	Position
1.	Capt Dato Meor (Chairman)	Pilot's Operator
2.	Amir Abdullah	GAM / Deputy CAMO Manager
3.	Mohd Hasnan Bin Din	GAM / LAE
4.	Ihsan Masri	GAM/ CAMO Planner
5.	Mohd Yasir	GAM / Technical Services

No.	Agenda/Matters Discussed	Action By	Remarks
1	OPENING REMARKS		
1.1	Greetings and introduction by Chairman	For Information	Nil
2	Drafted GASSB/CAMO/AMP/EC155B Issue 1, Revision 0 Review		
2.1	Aircraft Maintenance Programme (AMP) reviewed based on the drafted GASSB/CAMO/AMP/EC155B Issue 1, Revision 0 prepared by GAM.	GAM	For information
2.2	AMP developed in accordance with ORION EC155 AMPI Chapter 4 ALS NR007 dated 22/1/2021 and Chapter 5 MSM NR010 dated 22/1/2021	GAM	For information
2.3	Chapter 20.0: Daily check Daily checks updated as per aircraft configuration in accordance with related inspection from MSM, RFM AD & POST modification.	GAM	Operator noted with the information
3	DIFFERENCES WITH HRHSP/CAMO/AMP/EC155B		
3.1	 Chapter 12.0: Scheduled maintenance check and cycle, Page 9 of 11 Engine cleaning Engine cleaning task interval based on operating condition (Corrosive or salty atmosphere). Rinsing - Daily interval Chemical Cleaning - Every 100 FH interval External Wash - Weekly or Every 50FH interval 	GAM	Operator noted with the information



CONTINUING AIRWORTHINESS MANAGEMENT ORGANISATION MINUTES OF MEETING

No.	Agenda/Matters Discussed	Action By	Remarks
3.2	Chapter 17.0: Inspection Post Modification, Page 4 of 4		
	- additional of modification ELT Kannad 406 in accordance with GAM099/ICA.	GAM	Operator agreed
	- additional of modification exterior placard in accordance with GAM112/ICA.	GAM	
	 additional of modification Data plate and exterior placard in accordance with GAM123/ICA. 		
	Chapter 18.0: CAAM AND AD REQUIREMENT, Page 2 of 2		
	AD requirement		
3.3	- Additional of AD 2021-0170 which supersede AD 2020-0078 & AD 2019-267. No changes on task interval.	GAM	Operator noted with the information
	- AD 2021-0170 require to be perform as follows:-		
	Inspection: Every 10FH		
	Replacement: Every 500FH		
	Chapter 19.0: Operator requirement		
3.4	New chapter introduce to reserve inspection for operator requirement and operation.	GAM	Operator noted with the information
	Chapter 20.0: Daily check		
3.5	Additional of daily check for Data plate & exterior marking during pre-flight check in accordance with GAM123/ICA.	GAM	Operator noted with the information
4	Others		
4.1	New Revision GASSB/CAMO/AMP/EC155B Issue 1, Revision 0 to be submit as per discussion and review in meeting.	GAM	All the comments has been taken into account and AMP has been revised before submitting.
5	Closing		
5.1	Meeting adjourned at 11:30 am	NIL	For Information

Prepared by	Mohd Yasir bin Shapuan	Verified by	'Amir bin Abdullah
Signature	Jerry P.	Signature	ihni
Date	25 October 2021	Date	25 October 2021