



Nurulazhan Sallehuddin <azhan.gam@gmail.com>

SB139-738 - ATA 53-TAIL BOOM ASSY CORROSION PREVENTION IMPROVEMENT UPDATE

2 messages

Zulakmal Azhari Mohammad Shukry <zulakmal@galaxyaerospace.my>

22 December 2023 at 10:14

To: Izzati Azmi <izzatiazmi@galaxyaerospace.my>

Cc: Procurement <procurement@galaxyaerospace.my>, redzuan@galaxyaerospace.my, azhan@galaxyaerospace.my, saiful@galaxyaerospace.my, shazalie@galaxyaerospace.my, atira.galaxyaerospace@gmail.com, firdausdaud@mmea.gov.my, mohdraisohtman@yahoo.com, ismailmohamadon@mmea.gov.my

Salam Izzati,

Kindly assist to provide the latest update status of spare request for SB139-738 ATA 53 Tail Boom Assy Corrosion Prevention Improvement.

Your kind assistance is much appreciated. Thank you

Regards,

Zulakmal Azhari Mohammad Shukry

Production Planner & Control

*for and on behalf of***GALAXY AEROSPACE (M) SDN BHD**

No. A-01-02, Blok A, Bangunan Perdagangan Siera Ara Damansara, Jalan PJU 1A/5A, Ara Damansara, 47301 Petaling Jaya, Selangor.

+603-7455 0555 +603-7734 7526

Lot 11-14, MRO Centre, MIAC, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor.

+603-7734 7226 +603-7734 7526

Izzati Azmi <izzatiazmi@galaxyaerospace.my>

22 December 2023 at 11:26

To: Zulakmal Azhari Mohammad Shukry <zulakmal@galaxyaerospace.my>

Cc: Procurement <procurement@galaxyaerospace.my>, redzuan@galaxyaerospace.my, azhan@galaxyaerospace.my, saiful@galaxyaerospace.my, shazalie@galaxyaerospace.my, atira.galaxyaerospace@gmail.com, firdausdaud@mmea.gov.my, mohdraisohtman@yahoo.com, ismailmohamadon@mmea.gov.my

Hi Zul,

Below is the EDD for the spares,

Please refer below;

3G5318A63631	BONDING PLATE ASSY	3	EDD postponed to end Jan 2024	MMA-23-812
3G5355A09151	BONDING PLATE	3	EDD postponed to end Jan 2024	MMA-23-812
A298A04TW02	RIVET,BLIND,TITANIUM	10	Ready for collection	MMA-23-812
A428A08C05	SCREW,WASHER HEAD	3	Ready for collection	MMA-23-812

While for the following PN, the item is currently unavailable and the vendor is currently identify the suitable alternative. Once I received information on the alternative part number, I will let you know.

Part Number: 199-05-003 Type I, Class 1, Shape IIB - Sealant tape (C405)

Job: 4483 SBSB139-738 - ATA 53-TAIL BOOM ASSY CORROSION PREVENTION IMPROVEMENT

Thank you.

Regards,

Nor Izzati Azmi

Logistic & Procurement Executive

for and on behalf of

GALAXY AEROSPACE (M) SDN BHD



Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Darul Ehsan.

Website : www.galaxyaerospace.my

 +60377347226  +60377347526

From: Zulakmal Azhari Mohammad Shukry <zulakmal@galaxyaerospace.my>

Sent: Friday, December 22, 2023 10:15 AM

To: Izzati Azmi <izzatiazmi@galaxyaerospace.my>

Cc: Procurement <procurement@galaxyaerospace.my>; redzuan@galaxyaerospace.my; azhan@galaxyaerospace.my; saiful@galaxyaerospace.my; shazalie@galaxyaerospace.my; atira.galaxyaerospace@gmail.com; firdausdaud@mmea.gov.my; mohdraisohtman@yahoo.com; ismailmohamadon@mmea.gov.my

Subject: SB139-738 - ATA 53-TAIL BOOM ASSY CORROSION PREVENTION IMPROVEMENT UPDATE

Salam Izzati,

Kindly assist to provide the latest update status of spare request for SB139-738 ATA 53 Tail Boom Assy Corrosion Prevention Improvement.

Your kind assistance is much appreciated. Thank you

Regards,

Zulakmal Azhari Mohammad Shukry

Production Planner & Control

for and on behalf of

GALAXY AEROSPACE (M) SDN BHD

[Quoted text hidden]

[Quoted text hidden]