


**CIVIL AVIATION AUTHORITY OF MALAYSIA**  
**AIRWORTHINESS DIVISION**

<b>NON COMPLIANCE RECORD</b>	Reference No. : NCR/AW/AS/ARS/2021/11/SURV 2022/01
<b>Organisation</b> : GALAXY AEROSPACE MALAYSIA <b>Area</b> : AIRWORTHINESS REVIEW	<b>NCR level :</b> 2
<b>1. Requirement:</b> CAD 6802 para 9.1.1	
<b>2. Encountered Condition.</b>  During ARS surveillance to an approved signatory Mohamad Syafiq (CAAM/AW/AS/ARS/2021/11) at Galaxy Aerospace Malaysia on 1 August 2022, found a discrepancy in ARR ref no: GAM/ARR/PMB/22/08 para 3.10, Noise Certificate. As stated in the ARR report, the noise certificate was issued on 16 Mar 2020, but a physical check on aircraft bearing 9M-PMB, found the noise certificate was issued on 19 August 2016.	
	
<b>Auditor name &amp; Signature:</b> AZ AFZAN ZUHARI BIN MOHAMED AZHAR <b>Date:</b> 02 August 2022	
<b>3. Corrective Action.(see note #1)</b>          	
<b>Auditee name &amp; Signature:</b>	<b>Date:</b>
<b>4.The corrective action has been reviewed, verified and found to be:</b> (see notes #2 & #3)	
<b>ACCEPTABLE / UNACCEPTABLE</b>	
<b>If unacceptable, reason for rejecting the corrective action:</b>          	
<b>Auditor Name &amp; Signature:</b>	
<b>Date :</b>	

AWD/002  
030303

- Notes :
1. Auditee to respond to this NCR form stating the intended corrective action return to CAAM within 14 days after receiving this report.
  2. If the corrective action is not acceptable raise a revised NCR using the same reference number suffixed with revision number.
  3. If the corrective action is acceptable, the NCR is closed.