




**MODIFICATION RECORD SHEET – AIRWORTHINESS DIRECTIVE**

	DOCUMENT TITLE: EASA AIRWORTHINESS DIRECTIVE – AIRFRAME	A/C TYPE: AW139	A/C REGN: 9M-YTL	A/C S/N: 41358	APU TYPE: -
		ENG. TYPE PT6C-67C	ENG #1 S/N: PCE-KB1443	ENG #2 S/N: PCE-KB1457	APU S/N: -

NO.	AD NO.	SB REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
41	2015-0226R5 DATE: 2020-07-23	-	ATA 25 - EQUIPMENT / FURNISHINGS - HOIST - TEST / REPLACEMENT	TIC-AW139-20-116 DATED: 25.07.2020	NOT APPLICABLE DUE TO COMPONENT NOT FITTED TO AIRCRAFT.
42	2020-0185 DATE: 2020-08-19	-	ATA 25 – EQUIPMENT / FURNISHINGS – LIFE RAFT RESERVOIR AND ACTUATOR CABLE – REPLACEMENT / INSPECTION	TIC-AW139-20-127 DATED: 21.08.2020	NOT APPLICABLE DUE TO AFFECTED FLOATATION SYSTEM (P/N) 4G9560F00111 OR P/N 4G9560F00211 NOT INSTALLED ON RESPECTIVE AIRCRAFT.
43	2020-0191 DATE: 04.09.2020	139-633 REV A	ATA 25 - EQUIPMENT / FURNISHINGS - FORWARD FACING CENTRAL SEAT(S) - REMOVAL	TIC-AW139-20-132 DATED: 07.09.2020	NOT APPLICABLE DUE TO AIRCRAFT SEAT CONFIGURATION NOT INSTALLED FACING FWD.

- END OF PAGE -

NORSHAHEERA ILIYU BINTI MUSTAFA  
 Senior Technical Record  
 Galaxy Aerospace (M) Sdn Bhd  
 (1040262-D)

PREPARED BY : \_\_\_\_\_ VERIFIED BY : \_\_\_\_\_  
 DATE : 30/10/2020 DATE : \_\_\_\_\_  
 SIGN & STAMP :   SIGN & STAMP : \_\_\_\_\_

GAM/CAMO-017R1

ENG 2 AL    ENG 1 SB    ENG 1 A    AF SB