
NCR 02

Work Pack Ref. 9M-PTB-16078 and Aircraft Journey Log (AJL) S/N 001329-001335 were reviewed and found discrepancies as per below details:

No	Document	Remarks				
1.	Workpack 9M-PTB- 16078	Incomplete records. Refer Appendix 2.				
2.	Worksheet 16078-001, Page 10 of 30, item 30	Found UMC-PTB-23-028 was raised from this task. Review UMC, found information transferred was not as per CAMO instruction. Refer Appendix 4.				
3.	Worksheet 16078-007, Page 5 of 10, Item 12	Remarks, tech, eng. CRS column was left blank. Refer Appendix 6.				
4.	Worksheet 16078-011, Page 1 of 1, Item 2 and 3	Remarks, tech and eng CRS, CRS were left blank. Parts Report was left blank. Refer Appendix 7.				
5.	Work Pack No.: 9M- PTB-16078	Tools Report was left blank. Refer Appendix 8.				
No.	AJL No.	AJL No. Remarks				
1.	001329	4 th copy: AJL Copy (yellow color), was not stamped with AMO Approval No, Authority column for item 1 and 2 were not stamped. Refer Appendix 9.				
2.	001333	Rectification taken column, found date and time column were left blank. Refer Appendix 10.				
3.	001332-001335	Incomplete documentation even though BMRC for this package had been issued.				




A	udit Report
Report No.	IAR-2023/064
Area / Scope	GAM-AMO B300
Date of audit	8 & 11 Sept 2023



Appendix 2: Incomplete records of Workpack 9M-PTB-16078.



A	udit Report
Report No.	IAR-2023/064
Area / Scope	GAM-AMO B300
Date of audit	8 & 11 Sept 2023




Appendix 3: CRS column was left blank.



A	udit Report
Report No.	IAR-2023/064
Area / Scope	GAM-AMO B300
Date of audit	8 & 11 Sept 2023




Appendix 4: Incomplete information transferred.



Appendix 5: Remarks column was left blank.



A	udit Report
Report No.	IAR-2023/064
Area / Scope	GAM-AMO B300
Date of audit	8 & 11 Sept 2023



Appendix 6: The remarks, tech, eng. CRS column was left blank.



A	udit Report
Report No.	IAR-2023/064
Area / Scope	GAM-AMO B300
Date of audit	8 & 11 Sept 2023

CLIENT/C	OWNER: ROYAL MALAYSIA POLICE T TYPE: B300 (SKA350) ATION: 9M-PTB	AIRCRAFT #1 ENGINE:	OSPACE (M, SON, Bi- relicopies Centre Andre Andre Anzi Stath Andre Andre Anzi Stath Angret, 4724 4 7226 Fax: +603 7 errospace my exquiry SERIAL NO. FL-593 PCE-PK1183	HOURS REFER W	LDG/CYCLE ORKPACK ORKPACK		WORKSHEET NO: 16078-011 WORK/INSP/DESC: FUEL NOZZLES WORKPACK REF: 9M-PTB-16078 AJL REF NO: REFER WORKPACK							
	CILITY: WMSA	#2 ENGINE:	PCE-PK0970	REFER W	ORKPACK NG / N1 NF	/N2	SHEET:	1 OF	1					
Reason I 400 FH EN AIRCRAFT REVISION	REFER WORKPACK OUT: REFER WORKPACK for raising: GINE NUMBER 2 FUEL NOZZLES INSPE MAINTENANCE PROGRAMME: RMPAO 1 DATED JUNE-16-2023, OR LATER APF	CTION TO BE CARE	ISSUE 2 TEMPORA	DANCE WITH RY		Other requirements/information: NOT APPLICABLE The CRS Date								
Item	SWEIS AFH Technician * Eng. CRS Date													
1	ENGINE INTERNALS - HOT SEC													
	EXAMINE WITH BOROSCOPE (R		8 H)											
	INTERVAL: IN CONJUNCTION V (REF. 3.B (9) REFERENCE: EMM 72-00-00 TA	BLE 601 PARA 2	B		CTION TEST		ALC AND A STATE OF THE STATE OF		2673					
	REMARKS: WORK CARRIED OUT AND FOUND SATISFACTORY RECTIFICATION REFERENCE:													
2.	SYSTEMS – FUEL SYSTEM LEAK TEST AND FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (REF. 73-10-05, INSPECTION /CHECK)													
	INTERVAL: SEE NOTES NOTE: 1. DO THE PERIODIC BORESCOPE INSPECTION OF THE HOT SECTION COMPONENTS IN CONJUNCTION WITH THESE TESTS (REF. PARA. 2.8.). NOTE: 2. FOR IMPROVED HOT SECTION DURABILITY, IT IS RECOMMENDED THAT THE FUEL.													
	NOTE: 2. FOR IMPROVED HOT SECTION DURABILITY, IT IS RECOMMENDED THAT THE FUEL NOZZLE ASSEMBLIES BE INSPECTED ON A ROUTINE BASIS ACCORDING TO: (EMM 72-00-00 TABLE 801 PARA 3-B-9(b) REFERENCE: EMM 72-00-00 TABLE 601 PARA 3-B REMARKS: WORK CARRIED OUT AND FOUND SATISFACTORY RECTIFICATION REFERENCE:													
3.	SYSTEMS – FUEL SYSTEM ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM GREE CHARTER 73-10-05 FUEL MANIFOLD, CLEANING/PAINTING).													
	(REF. CHAPTER 73-10-05, FUEL MANIFOLD, CLEANING/PAINTING). INTERVAL: SEE NOTES													
	NOTE: 1. WHERE FUEL QUALITY IS NOT SURE, AND FOR OPERATORS NEW TO PT64 OPERATION, CLEANING/INSPECTION IS RECOMMENDED AT 200 HOURS INITIALLY, WITH EXTENSION, BASED ON THE OPERATORS EXPERIENCE AND REJECTION RATE, NOT MORE THAN 200 HOURS.													
	NOTE: 2. FOR OTHER OPERA' WITH EXTENSION BASED ON THAN 200 HOURS.	NOTE: 2. FOR OTHER OPERATORS, INSPECTION IS RECOMMENDED AT 400 HOURS INITIALLY, MITH EXTENSION BASED ON THE OPERATORS EXPERIENCE AND REJECTION RATE, NOT MORE THAN 200 HOURS.												
	REFERENCE : EMM 72-00-00 1			ORY										
	RECTIFICATIO	N REFERENCE:												
the	ertifies that the work specified above aircraft / aircraft component is con- ertifies that the work specified above I in respect to that work the aircraft	a aveant as other	rwise specified, v	ras carried or	ut in accordance with	CAA Mal	aysia Requireme	ints and in respect t	o that work					
							PILL							
1 200	K ▼ WHERE APPLICABLE					-								

Appendix 7(a): Remarks, tech and eng CRS, CRS were left blank.




A	udit Report
Report No.	IAR-2023/064
Area / Scope	GAM-AMO B300
Date of audit	8 & 11 Sept 2023

REGISTRATION: 9M-PTB #1 ENGINE: PGE-PK193 REFER WORKPACK #2 ENGINE: PCE-PK0970 REFER WORKPACK AJL REF NO: SHEET: Reason for raising: Refer workpack OUT; REFER WORKPACK Reason for raising: Raised by and date: Other requirements/in	9M-PTB-16078 REFER WORKPACK 1 OF 1 ts/information: DT APPLICABLE
AIRCRAFT TYPE: B300 (SKA350) BF1 ENGINE: PCE-PK1183 REFER WORKPACK BASE/FACULTY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK BROSSON for raising: AUX OF HE ROINE EYELL NOZZLES INSPECTION TO BE CARRY OUT IN ACCORDANCE WITH AIRCRAFT MAINTENANCE PROGRAMME: RMPAOF/CANO/MAP/B300 ISSUE 2 TEMPORARY AIRCRAFT MAINTENANCE PROGRAMME: RMPAOF/CANO/MAP/B300 ISSUE 2 TEMPORARY DUE AT: 599-825 APH BEAT NO. BESTORION DESCRIPTION DE LA TEMPORA DE LES DESCRIPTION DE LA TEMPORA DE LA	REFER WORKPACK 1 OF 1 Is/information: DT APPLICABLE
#2 ENGINE: PCE-PK0970 REFER WORKPACK AJL RIE P.NO.: SHEET: Reason for raising: Woo FH ENGINE NUMBER 2 FUEL NOZZLES INSPECTION TO BE CARRY OUT IN ACCORDANCE WITH AIRCRAFT MAINTENANCE PROGRAMME: RMPAOF/CAMO/AMP/B300 ISSUE 2 TEMPORARY AJL RIE P.NO.: SHEET: Other requirements/in NOT AI AIRCRAFT MAINTENANCE PROGRAMME: RMPAOF/CAMO/AMP/B300 ISSUE 2 TEMPORARY Zeinol Abidin 15/08/2023 DUE AT: 5998-23 APH DESCRICTION REFER WORKPACK AJL RIE P.NO.: SHEET: Other requirements/in NOT AI Lifed from Information REFER WORKPACK OTHER PROGRAMME: MPAOF/CAMO/AMP/B300 ISSUE 2 TEMPORARY Zeinol Abidin 15/08/2023 Lifed from Information REFER WORKPACK OTHER PROGRAMME: MPAOF/CAMO/AMP/B300 ISSUE 2 TEMPORARY Zeinol Abidin 15/08/2023 Lifed from Information REFER WORKPACK OTHER PROGRAMME: MPAOF/CAMO/AMP/B300 ISSUE 2 TEMPORARY Zeinol Abidin 15/08/2023 Lifed from Information Lifed from	1 OF 1 ts/information: DT APPLICABLE
ATE IN: REFER WORKPACK QUT: REFER WORKPACK Reason for raising: Reason for raising: Raised by and date: CAMO; Nurul Husna Zeinol Abidin 15/08/2023 DUE AT: 5998-25 APH Description Description Description Description Reason Description Reason Reason Description Reason Re	ts/information: DT APPLICABLE
100 FH ENGINE NUMBER 2 FUEL NOZZLES INSPECTION TO BE CARRY OUT IN ACCORDANCE WITH AIRCRAFT MAINTENANCE PROGRAMME: RMPAOFICAMOMAPPB300 ISSUE 2 TEMPORARY REVISION 1 DATED JUNE-15-2023, OR LATER APPROVED REVISIONS. DUE AT: 5998:25 APP DEED TO DEED TO DESCRIPTION OF THE PROPERTY OF THE P	mation Release Reference
Item Part No Description Oty Position Reason Tentro DI E TIME	Malease Perference
NAME FIRM SIGN & APPROVAL	DATE
Can L. Can	
MOHO ZATINOIKIN	06/09/00
Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Require that work the aircraft / aircraft component is considered ready for release to service. Certifies that the work specified above, except as otherwise specified, was carried out in accordance with	06/09/000
and in respect to that work the aircraft / aircraft component is considered ready for release to service.	

Appendix 7(b): Parts Report was left blank.



A	udit Report
Report No.	IAR-2023/064
Area / Scope	GAM-AMO B300
Date of audit	8 & 11 Sept 2023



Appendix 8: Tools Report for Work Pack No.: 9M-PTB-16078 was left blank.



A	udit Report
Report No.	IAR-2023/064
Area / Scope	GAM-AMO B300
Date of audit	8 & 11 Sept 2023

	CLIENT/OPERAT	AVSIAN POLICE ATTON UNIT SUP REVIOUS BARR C. C. P. P. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2.	AIRC	RAFT TYP	E A	JRCRAFT R	EG. AIRCRAFT SN B				BASE	BASE DATE				DAILY INSPECTION							
ROY	AL MALAYSIAN UR OPERATION I	POLICE	SUPER	B300 KING AIR	350 100	PIR	10	60.0	193	1, 10,	k K	10	108104	O N	AME	4				Part I			
1000	PREVIOUS BINRC NEXT CALENDAR INSP		United States			NEXT HOURS INSP		MEASURING UNITS		UTH	TAIZ			66									
REF				DOS INSP		CHARTS				15E 2			The second second	SERVICE STATE	IGN	1/2		(FOI	AIRCRAFT JOURNEY				
DATE				DUE	3 105	203		DUE		TEST			1000000	Section 1	IME	100	30		GE SERIAL		13		
FLT.	SIGN			TIME	PILO		CO-PILOT		OBSERVE	R	FROM	то		TIN		TOTAL	LANDING		EHOURS	ENGI	NE CYC		
200	MAN	PETT	145	800	- Scupe	WE THE	The state of the s	COLUMN EVE	minals of	5000	JP.KK	WELL	TAKE	NAME OF STREET	DING	FLT	-	ENG 1	ENG 2	ENG 1	E		
100	or believe	10.9.4	75.		NOUVE B		CAN DE	-	UE CA		WELLING.	Wmsa	1340	1,000,00		2:05	1	3 7	2.01	The state of the s	1		
1000 N	CONTRACTOR OF THE PARTY OF THE			100		Manie Contract	47.780	15000	SUISCO.	all .	30 73 7				17.3				2:50	- 1	1.1.		
1000 m	CHANGE CO.	No.			100		1811/1		2000			AJL w	as no	ot sta	mp	ed w	/ith t	he A	MO				
	- William	1000		1 1 1 1								A		10			-		1000	1	3 100		
-	SEASON OF THE PARTY OF THE PART	100	1	10000				13 13	F 2. 7.			Appro	vair	vo.						10000			
ES.		1000	-					100	SE NO	500 5	- 116	1			and the			LO COL	-		1		
				-	200							Autho	milita no	colum	TARE	were	left	hlan	(0 25	- 2	3		
											100		TOTA	L BEFORE	FLIGHT	Sharak	1530	51(L) 35					
FLT.							TOTAL CARRY FORWARD STATE 15 45				4533												
NO.	LH				AUX RH	LH	F			All	X RH	14					The state of the s		OIL UPLIF		-		
1000	1901	1840		3 2/8	No.					le(c)	-	7/20/05	run	AUX L		AUX RH	ENG 1 LH	ENG 1	RH EN	NG 2 LH	ENG		
(A)((1)	June 1	17,400	100	7	-		1 13		5	115	REE .	2440000	177bc	1 1 3		125				3			
100		T. Carlo			1.5	11000000			-					1					200		100		
	5997 F	701.5	-							-									72 50				
200	HE STORY	BEKMA		- 3	1000							-				1		-		-			
200	CHANGE TO	Angel -				Bear						200	- 1				111111111111111111111111111111111111111	The second	000				
Section 1	A COLUMN						DIL OF I							1000					100 000	1000			
NO.	RECORD 0	F DEFECT(S). ENTER	'NIL' IF N	O DEFECT FO	UND	SIGN			NO.		The Later	RECT	TIFICATION	E) TAN	THE STATE OF THE S			Section 1				
	2000		6719.6		THE WAY	STATE OF THE PARTY OF	STH.	12912	4950	Al-	10000	(2) 20x101112			o) IAN	C.FE		MF	R SIGN"	AUTH DA	TE 1		
EEE .	P. P. W. Land	Calle	100- 1		7760 x 700		200	1/1	SHAT.	12	No.	NACT DE							AV.	16	2/31		
Ant E	South Lane		1 30 51	w. G. 160	1 0000	1 700 /	111	(SHE		100	Mayn		1000	The same of	500				1990	24	100		
1				KIM ION) Luper	100	100	- Ash	(A)	m	MARK	CACPI	Es an	1 AS	PUR	910-	PIR -	163100	COLVS	-			
	ASSESSED	1						(8)	Deliver.	250	ANC	forms	Popl L	FACTOR	ty.	THE IS	1	6370	- In In	F (FEEDOM	(8A3)		
M2 人	INCHAIT FI	PROTECTION OF DEFECT FOUND PR	1		TOTAL TOTAL			SHA															
00	MINDIONN,	CONTAN	VS D	CHADY	2	200	100		1Coc	M	TAN.	CARAL	(no. (t	phone	0	SATSI	Anton	1 1	F	1	3		
ALC: NO	RCKALL FIR	TO TOWN	DASLE	AGLIMA	ISE DAMP	LUND	ply	S Control	1200	145	TACL	LA M	- 416	-163			The state of the s		200		2/11		
MIAMA	TEMANOR	EL VID	DATABL	SE CT	1000	SEC. 1		Control of the contro			REIL	K MARIE	P78- 1	FULL S	2 51	MISTAC	Tof 4	2	4	122/2	15 14		
	ASE (MR) TEMENT	THE WO	RK RECO	DRDED AB	OVE HAS REE	MCADDIES	-		The Party of the P	Name and Address of the Owner, where the Owner, which is the Own	-	- Inch	Se ver	DOWN					101 16	PP 1	-		

Appendix 9: AJL was not stamped with the AMO Approval No. and Authority column were left blank.



Audit Report									
Report No.	IAR-2023/064								
Area / Scope	GAM-AMO B300								
Date of audit	8 & 11 Sept 2023								

CLIENT/OPERATOR AIRCRAFT TYPE AIRCRAFT REG ROYAL MALAYSIAN POLICE B300 AIR OPERATION UNIT SUPER KING AIR 350 MM - PT & PREVIOUS BARC MEXT CAN ENTRY WAY NEXT CAN ENTRY WAY TO SUPER KING AIR 350 MM - PT & TO SUPER KING AI				TSN		BASE			TE		DAILY INSPECTION				, de						
			JF 145	3	WMSA					NAME					2	32					
REF	2000000		INSP	E-CHARTS			men	INSP		KT HOURS INSP		Total Street	RING UNITS	-				AIRC	RAFT J	DURNEY	100
DATE			DUE	20/09	123		- 2000000000000000000000000000000000000	DUE				FUEL	LBS	SIGN				AIRCRAFT JOURNEY LOS			
FLT.	SIGN AL			PILOT		CO-PILOT		OBSERVER				OIC	QT	TIME			ENGIN	E HOURS		OO:	L33
								COSERVER		FROM	TO	TA	AKEOFF	LANDING	FLT	LANDING	ENG 1	ENG		ENG 1	ENG 2
						-															
					-	2000		FEED OF		No.	TOTAL	FLIGHT	HOURS IN	THIS PAGE							
						(Active)							DOUBLE DOUBLE		5486:35	4524	3(23:30	6015:	51 10	42	3409
FLT. NO.	FUEL REMAINING FUEL UPLIFT												TAL CARRY	FORWARD							
	LH	RH	AUX LH	AUX RH	LH	R				RH	LH	RH	UEL TOTAL	CLH	AUX RH	ENG 1 LI	ENG	OIL UP	ENG 2	нЕ	NG 2 RH
NO.	pecana	OF DEFFOR	(S). ENTER 'HIL' IF N			PILOT/E	ENGINEER		100000							FUL					,,
	ADAS+ 1			O DEFECT FOUN	(D	SIGN	ANTH	TIME	NO.	-			ECTIFICATI				MR	SIGN"	AUTH	DATE	TIME
ZIPANI		My	(100 M)	0100	Leat	CEF	ER 9M-	PTR-	1600x	10 84	TISFACT	ory.	2	13		8/1/23	1500				
42	C 37AH9	3	(Fame)	0850	m2	749	W CARRIE	ZA C	ASR WP	am-	חפו- מדי	18-00		The state of							
M3	12 MONT	lu	1	0800		AND	FOUND !	SATISE	=ACTORY					P	W2						
		177		0800	17.3	SATI	CARRIGO	OUT	AS PER	911-	PTB-160	79 FOU	ND /	die	9	EM123	1100				
M H	MING LOC	ikens i	HSPECTION			de	3(411)	arco	my	TASK	CARRIED	001	AS PE	R 9W	- PTB - I	6078 -	003 0	6.		704	1000
m 5	OUAL AFT	0	The same of the sa			Fou	ITAZ GMI	SPACT	ropy.				1	5		77/28	7000				
	The second second																				
R	AINTENANCE SLEASE (MR) STATEMENT	THE V	WORK RECORDED A	BOVE HAS BEEN	CARRIE	OUT IN AC	CORDAN	CE WITH T	HE REQ	JIREME.	NTS OF THE M	CAR FO	R THE TIME	BEING IN	FORCE AND	IN THAT RE	SPECT THE	AIRCRA	FT/EO	PMENT	15
	MEMENT							CO	MSIDERI	DEITE	OR RELEASE	TO SERV	nce.								
	LABIN					OR ALL	74.76										1ST CO	PY: CAM	O TECH	NICAL R	ECORD

Appendix 10: Incomplete documentation even though BMRC for this package had been issued.