

Document Reference

Document ID	PSE/TQ/2024/144379	Contact	Zulkarnean Ibrahim
Your Code Reference		Subject	9M-PMD SN 31809 MAIN ROTOR BLADE 3G6210A00131 HIT THE HANGAR BEAM.
Topic	TECHNICAL	Subtopic	OTHER
Issue	SEE TQ DETAIL	Team Legal Entity	Italy

Contact Details

Customer Description	GALAXY HELICOPTERS(M) SDN BHD	Customer ID	0006005700
Email	zulkarnaen@galaxyaerospace.my		

Contacts List

First Name	Last Name	Email	User Type
TECHNICAL	SERVICES	tech.services@galaxyaerospace.my	Engineering Officer

Customer Service

Priority	Routine	Creation On (UTC)	28/02/2024
Resolve By (UTC)	14/03/2024	Leonardo Closure Date (UTC)	
Additional Note			

Helicopter Data

ATA Code	62	Description	MAIN ROTOR(S)
Helicopter S/N	NC0031809	Aircraft Tail Number	9M-PMD
Helicopter Line	AW139	Helicopter Model	AW139
Repair Instruction Query	False		

Part Number	Component S/N	Component F/H	On (Date)(UTC)
-			

Flight Hours	FH Last Update	Create date
1777,22	27/09/2023	27/09/2023

Ticket Description

Dear Leonardo Helicopter,

While towing aircraft 9M-PMD (MSN 31809) Main Rotor Blade hit the hangar beam, causing the trailing edge tip to be lightly damaged.

Component Detail

Name: Main Rotor Blade

Part Number: 3G6210A00131

Serial Number: AW4236E

Component Hours: 1917:15 FH

Component Landing Cycle: 3347 Cycle

The picture attached is a damaged tip blade.

The Occurrence report has been sent to the Local Authority (CAAM). Please find the document attached for your perusal.

Thank you.

History Log

Closing Note

Ticket Attachments

Attachment's Name	Uploading Date
Ticket_PSE_TQ_2024_144379.pdf	28/02/2024
MRB AW4236E - 2.jpg	28/02/2024
MOR18024.pdf	28/02/2024
MRB AW4236E - 7.jpg	28/02/2024
MRB AW4236E - 5.jpg	28/02/2024
MRB AW4236E - 3.jpg	28/02/2024
MRB AW4236E - 1.jpg	28/02/2024

MRB AW4236E - 4.jpg	28/02/2024
GAM_Q-038_R2- _GAM_Occurrence_Reports_20210824_012912.pdf	28/02/2024
MRB AW4236E - 6.jpg	28/02/2024