

Continuing Airworthiness Notice (CAN)		

CAN No. / Rev No.	CAN 56 / R0
Date	8-Mar-2023

To : GAM CAMO Personnel and Contracted AMO Personnel

CC : GAM Accountable Manager, GAM Quality Assurance Manager, GAM

Engineering Manager

From : Continuing Airworthiness Management (CAM) Manager

Subject: Additional Instruction for Completing AJL

1. REFERENCE

a. GAM/CAAM/CAME Issue 3 Revision 1 or later approved revision.

b. GAM/CAMO/CAMP Issue 2 Revision 1 or later approved revision.

2. APPLICABILITY

a. All aircraft managed by GAM CAMO

3. INTRODUCTION

- a. During Product Audit, QA department has raised an observation finding that the AJL was not properly filled up as per the instruction for completing form.
- b. This notice is raised to introduce the upcoming additional instruction and clarification required to ensure compliance with the above instruction.
- c. The compliance to these instructions shall be effective 9 March 2023 and shall be integrated into the upcoming revision of the AJL and instruction for completing form.

4. REQUIREMENT

- a. In the "record of defects(s)" column, the pilot is required to enter the following information:
 - i. any defect found during pre-flight inspection; or
 - ii. any defect that occurred during the flight conducted; or
 - iii. "NIL" for no defect found or occurred during the flight conducted.
- b. In the "record of defect(s)" column, for maintenance activity, engineer is required to enter the following information:
 - i. any defect found during Airworthiness Check / Pre-Flight Check / Daily Check.
 - ii. summary of scheduled maintenance performed on the aircraft.
- c. In the "rectification(s)" column, engineer is required to enter the following information:
 - i. rectification action performed to rectify the defect; or
 - ii. deferred defect action for the defect that was deferred as per MEL; or



Continuing Airworthiness Notice	
(CAN)	

CAN No. / Rev No.	CAN 56 / R0
Date	8-Mar-2023

- iii. "NOTED" for "NIL" entry in the "record of defect(s)" column at the first opportunity (eg: when the aircraft is back to base after operation away from base).
- d. All entries in the "rectification(s)" column shall have the same identification number as per the "record of defect(s)" identification number.
- e. Engineer shall ensure that the aircraft shall not be released to service when there is a defect recorded in the "record of defect(s)" column until the defect has been rectified or deferred as per MEL.

Kindly be informed and adhere to the requirement.

Zaty Nadhira binti Mohamed Zuhari

Continuing Airworthiness Management Manager