



Syed Mohd Rastam Jamalulail Syed Ikmal Hashim <rastam.gam@gmail.com>

GAM-SC/23/0052-Hangar Roof Leaking

2 messages

Syed Mohd Rastam Jamalulail Syed Ikmal Hashim <rastam@galaxyaerospace.my> 31 October 2023 at 16:03

To: ameera.diyana@unikl.edu.my, Suhaili Mohd Samingan <suhailims@unikl.edu.my>, Samsi Ismail <samsi@galaxyaerospace.my>, Syazwin Mohd Seth <syazwin@galaxyaerospace.my>, Azillah Bin Matap <azillah@galaxyaerospace.my>, Mohd Muqoddim Mohd Shakib <muqoddim@galaxyaerospace.my>, Muhammad Bin Mohd Taib <muhammad@galaxyaerospace.my>, Safety Department <safety@galaxyaerospace.my>

Dear Pn. Ameera.

Hope this email finds you well.

We received a report regarding a roof leak on the right side of hangar 2 near the exit door. The leaking is so severe, that the water flows down into the electrical conduit and exits from the electrical power point. Some of our aircraft parts need to be relocated from the area due to water heavy flow coming from the roof. To include, one of our security cameras was down due to an electrical short circuit.

We really need your kind attention regarding this matter to prevent any other incident from occurring in the near future.

Attached with this email is the hazard report for your kind reference.

Thank you

Kind Regards,

Syed Mohd Rastam Jamalolail Syed Ikmal Hashim

Safety

for and on behalf of

GALAXY AEROSPACE (M) SDN BHD



Lot 11-14, MRO Centre, Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Darul Ehsan.

Website : www.galaxyaerospace.my

+60377347226 +60377347526

2 attachments

GAM-SC-23-0052-CCTVpowerSupply-01.pdf
311K

WaterResidueAtMIAT-pic.pdf
601K

Ameera Diyana Mohd Salahuddin <ameera.diyana@unikl.edu.my> 31 October 2023 at 17:22

To: Syed Mohd Rastam Jamalulail Syed Ikmal Hashim <rastam@galaxyaerospace.my>, Suhaili Mohd Samingan <suhailims@unikl.edu.my>, Samsi Ismail <samsi@galaxyaerospace.my>, Syazwin Mohd Seth <syazwin@galaxyaerospace.my>, Azillah Bin Matap <azillah@galaxyaerospace.my>, Mohd Muqoddim Mohd Shakib <muqoddim@galaxyaerospace.my>, Muhammad Bin Mohd Taib <muhammad@galaxyaerospace.my>, Safety Department <safety@galaxyaerospace.my>, Anuar Berahim <anuar@unikl.edu.my>, Mokhtar Mohd Shah <mokhtar@unikl.edu.my>

Dear Encik Syed,

Your email earlier refers.

The report regarding a severe roof leak on the right side of Hangar 2, near the exit door with water flowing into the electrical conduit and affecting the electrical power point, is a matter of serious concern. It is also alarming to hear about the need to relocate aircraft parts due to the heavy water flow and the security camera outage caused by an electrical short circuit.

We understand the urgency and importance of this matter in preventing any further incidents. Our team will investigate the issue promptly and take the necessary actions to prevent a recurrence.

Thank you for attaching the hazard report; it will be a valuable reference in our assessment and resolution process.

We will keep you updated on our progress and any immediate steps that need to be taken. Safety is our top priority, and we appreciate your diligence in reporting this issue. If you have any additional information or observations related to this incident, please feel free to share them with us.

Once again, thank you for bringing this to our attention, and please rest assured that we are committed to resolving this matter soonest possible.

Thank you.

**Best Regards,
Meera**

From: Syed Mohd Rastam Jamalulail Syed Ikmal Hashim <rastam@galaxyaerospace.my>

Sent: Tuesday, October 31, 2023 1:03 AM

To: Ameera Diyana Mohd Salahuddin <ameera.diyana@unikl.edu.my>; Suhaili Mohd Samingan <suhailims@unikl.edu.my>; Samsi Ismail <samsi@galaxyaerospace.my>; Syazwin Mohd Seth <syazwin@galaxyaerospace.my>; Azillah Bin Matap <azillah@galaxyaerospace.my>; Mohd Muqoddim Mohd Shakib <muqoddim@galaxyaerospace.my>; Muhammad Bin Mohd Taib <muhammad@galaxyaerospace.my>; Safety Department <safety@galaxyaerospace.my>

Subject: GAM-SC/23/0052-Hangar Roof Leaking

[Quoted text hidden]