



Syed Mohd Rastam Jamalulail Syed Ikmal Hashim &lt;rastam.gam@gmail.com&gt;

**GAM-ENG/SC/23/0002 // PIPE LINE FOR WATER DRAIN FOUND LEAKING DURING HEAVY RAINING.**

6 messages

**Syed Mohd Rastam Jamalulail Syed Ikmal Hashim** <rastam@galaxyaerospace.my> 25 January 2023 at 12:51  
To: Mohd Eqbal Ab Rahim <mohd.eqbal@unikl.edu.my>  
Cc: Admin Team <admin@galaxyaerospace.my>, Safety Department <safety@galaxyaerospace.my>

Dear En Eqbal.  
Hope this email finds you well.

We received a report regarding a water drain leak at the hangar.  
Will keep you posted for any further details upon available.

Attached with this email is the hazard report raised for your reference.

Thank you  
Kind Regards,  
**Syed Mohd Rastam Jamalolail Syed Ikmal Hashim**  
Safety  
for and on behalf of  
**GALAXYAEROSPACE (M) SDN BHD**



Lot 11-14, MRO Centre, Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Darul Ehsan.  
Website : [www.galaxyaerospace.my](http://www.galaxyaerospace.my)  
 +60377347226 +60377347526

**GAM.SC.23.002.pdf**  
11K

**Mohd Eqbal Ab Rahim** <mohd.eqbal@unikl.edu.my> 25 January 2023 at 16:50  
To: Syed Mohd Rastam Jamalulail Syed Ikmal Hashim <rastam@galaxyaerospace.my>  
Cc: Admin Team <admin@galaxyaerospace.my>, Safety Department <safety@galaxyaerospace.my>

Dear En Syed,

Noted on your report. Appreciate if you could share the exact location and pictures of defect for our records and next action.

Thank you.

Best regards,

**Mohd Eqbal** | URSB Aeroservices Executive

UniKL Resources Sdn. Bhd. (URSB)

1016, Jalan Sultan Ismail,

50250 Kuala Lumpur, Malaysia.

Tel: +6018 663 0700 |Email: [mohd.eqbal@unikl.edu.my](mailto:mohd.eqbal@unikl.edu.my)



---

**From:** Syed Mohd Rastam Jamalulail Syed Ikmal Hashim <[rastam@galaxyaerospace.my](mailto:rastam@galaxyaerospace.my)>  
**Sent:** Wednesday, 25 January, 2023 12:51 PM  
**To:** Mohd Eqbal Ab Rahim <[mohd.eqbal@unikl.edu.my](mailto:mohd.eqbal@unikl.edu.my)>  
**Cc:** Admin Team <[admin@galaxyaerospace.my](mailto:admin@galaxyaerospace.my)>; Safety Department <[safety@galaxyaerospace.my](mailto:safety@galaxyaerospace.my)>  
**Subject:** GAM-ENG/SC/23/0002 // PIPE LINE FOR WATER DRAIN FOUND LEAKING DURING HEAVY RAINING.

You don't often get email from [rastam@galaxyaerospace.my](mailto:rastam@galaxyaerospace.my). [Learn why this is important](#)

Dear En Eqbal.

Hope this email finds you well.

We received a report regarding a water drain leak at the hangar.

Will keep you posted for any further details upon available.

Attached with this email is the hazard report raised for your reference.

Thank you

Kind Regards,  
**Syed Mohd Rastam Jamalolail Syed Ikmal Hashim**  
Safety  
*for and on behalf of*  
**GALAXY AEROSPACE (M) SDN BHD**

[Quoted text hidden]

---

**Syed Mohd Rastam Jamalulail Syed Ikmal Hashim** <[rastam@galaxyaerospace.my](mailto:rastam@galaxyaerospace.my)> 26 January 2023 at 12:01  
To: Mohd Eqbal Ab Rahim <[mohd.eqbal@unikl.edu.my](mailto:mohd.eqbal@unikl.edu.my)>  
Cc: Admin Team <[admin@galaxyaerospace.my](mailto:admin@galaxyaerospace.my)>, Safety Department <[safety@galaxyaerospace.my](mailto:safety@galaxyaerospace.my)>

Dear En. Eqbal.

Please find the pictures attached for your reference on the exact location of the water drain leaking area. It is about 21 meters from the aircraft entrance on the right-hand side hangar. The leak supposes to be dropped outside of the hangar, due to severe damage to the water drainage, and the water splashes into the hangar. Causing water to drain inside the electrical trunking conduit.

Your kind attention and assistance are highly appreciated.

Thank you.

Kind Regards,

**Syed Mohd Rastam Jamalolail Syed Ikmal Hashim**

Safety

for and on behalf of

**GALAXYAEROSPACE (M) SDN BHD**



Lot 11-14, MRO Centre, Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Darul Ehsan.

Website : [www.galaxyaerospace.my](http://www.galaxyaerospace.my)

☎ [+60377347226](tel:+60377347226) 📠 [+60377347526](tel:+60377347526)

[Quoted text hidden]

---


**3 attachments**



**Hangar2.p3.jpg**  
1447K



**Hangar2.p1.jpg**  
3140K



**Hangar2.p2.jpg**  
3009K

---

**Syed Mohd Rastam Jamalulail Syed Ikmal Hashim** <[rastam@galaxyaerospace.my](mailto:rastam@galaxyaerospace.my)>

31 January 2023 at 11:52

To: Mohd Eqbal Ab Rahim <[mohd.eqbal@unikl.edu.my](mailto:mohd.eqbal@unikl.edu.my)>

Cc: Admin Team <[admin@galaxyaerospace.my](mailto:admin@galaxyaerospace.my)>, Safety Department <[safety@galaxyaerospace.my](mailto:safety@galaxyaerospace.my)>

Dear En. Eqbal.

Hopefully this email finds you well.

Just need your updates on this matter. Do you need any further details kindly let me know.

Thank you

Kind Regards,

**Syed Mohd Rastam Jamalolail Syed Ikmal Hashim**

Safety

for and on behalf of

**GALAXYAEROSPACE (M) SDN BHD**

Lot 11-14, MRO Centre, Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Darul Ehsan.

Website : [www.galaxyaerospace.my](http://www.galaxyaerospace.my)

+60377347226 +60377347526

[Quoted text hidden]

---

**Mohd Eqbal Ab Rahim** <mohd.eqbal@unikl.edu.my>

31 January 2023 at 12:12

To: Syed Mohd Rastam Jamalulail Syed Ikmal Hashim <rastam@galaxyaerospace.my>

Cc: Admin Team <admin@galaxyaerospace.my>, Safety Department <safety@galaxyaerospace.my>

Salam En Syed,

The repair processes are currently on going starting last Friday, 27 January 2023. We have updated your team via En Muqaddim in the weekly meeting which been held yesterday.  
Thanks.

Best regards,

**Mohd Eqbal** | URSB Aeroservices Executive

UniKL Resources Sdn. Bhd. (URSB)

1016, Jalan Sultan Ismail,

50250 Kuala Lumpur, Malaysia.

Tel: +6018 663 0700 | Email: [mohd.eqbal@unikl.edu.my](mailto:mohd.eqbal@unikl.edu.my)

Image

---

**From:** Syed Mohd Rastam Jamalulail Syed Ikmal Hashim <rastam@galaxyaerospace.my>

**Sent:** Tuesday, January 31, 2023 11:52:45 AM

**To:** Mohd Eqbal Ab Rahim <mohd.eqbal@unikl.edu.my>

**Cc:** Admin Team <admin@galaxyaerospace.my>; Safety Department <safety@galaxyaerospace.my>

**Subject:** Re: GAM-ENG/SC/23/0002 // PIPE LINE FOR WATER DRAIN FOUND LEAKING DURING HEAVY RAINING.

[Quoted text hidden]

---

**Syed Mohd Rastam Jamalulail Syed Ikmal Hashim** <rastam@galaxyaerospace.my>

31 January 2023 at 16:24

To: Mohd Eqbal Ab Rahim <mohd.eqbal@unikl.edu.my>

Cc: Admin Team <admin@galaxyaerospace.my>, Safety Department <safety@galaxyaerospace.my>

Dear En. Eqbal.

Email well noted.  
Thank you for your kind response and support.

Kind Regards,

**Syed Mohd Rastam Jamalolail Syed Ikmal Hashim**

Safety

for and on behalf of

**GALAXYAEROSPACE (M) SDN BHD**



Lot 11-14, MRO Centre, Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Darul Ehsan.

Website : [www.galaxyaerospace.my](http://www.galaxyaerospace.my)

+60377347226 +60377347526

1/31/23, 4:24 PM

Gmail - GAM-ENG/SC/23/0002 // PIPE LINE FOR WATER DRAIN FOUND LEAKING DURING HEAVY RAINING.

[Quoted text hidden]