

**NAME:** Ahamd Hafiz Mohd Jamil

**STAFF No :** SL1M 241

## **OVERALL RECOMMENDATION**

Ahmad Hafidz have attended various trainings both technical and soft skills. He also had been involved in many projects in terms of data package preparation, testing and certification. He has shown a lot of enthusiasm, keenness, and spirit of teamwork in achieving task assigned. Hence, it is recommended to continue his service as a member of staff of DTS department.

## **SUPPORTING ACTIVITIES.**

### 1. PERFORMANCE MARCH TO MAY 2024

#### A. Task Accomplished.

- a. EC120 9M-GAS installation of GI275  
Data package, Ground testing, trouble shooting and certification.
  
- b. Bell206 LIDAR 206 L4  
Data package
  
- c. A109 9M-BOB  
Wiring Diagram GTN750xi, GTX355R, MD-302, DF 935-11
  
- d. Installation and removal of G5  
Data package

#### B. June 2023- Feb 2024

See enclosed.

### 2. TRAINING

See enclosed.

**Involvement in 8 months Protégé Duration**

Jobs	Involvement	PIC
GAM060 - Installation of Spidertracks on NOMAD N22B	Documentations, Drawings, Aircraft Visit, Justification	Ir Nizam Nazar
GAM061 - Installation of Spidertracks on Super King Air 200	Documentations, Drawings, Justification	Ir Nizam Nazar
GAM034 - Installation of Floorboard Rubber Mat on Superlynx 300 MK 100	Documentations	Ir Nizam Nazar
GAM047 - Defective Hand Hold RH Sliding Door Upper Rail Area Repair Superlynx 300 MK 100	DRAS Documentations	Ir Nizam Nazar
GAM271 - Removal of ELT Rescu 406SE and Installation of ELT RESCU 406SG on B737-800	Documentations	Ir Nizam Nazar
GAM035 – RH Sliding Door Upper Rail Panel Superlynx 300 MK 100	DRAS Documentations	Ir Nizam Nazar
GAM036 – Air intake Repair on Superlynx 300 MK 100	DRAS Documentations	Ir Nizam Nazar
GAM037 – Hydraulic Pump Drain Hose Repair Superlynx 300 MK 100	DRAS Documentations	Ir Nizam Nazar
GAM038 – Door Stopper Repair on Superlynx 300 MK 100	DRAS Documentations	Ir Nizam Nazar
GAM039 – IGB Casing Assembly Repair on Superlynx 300 MK 100	DRAS Documentations	Ir Nizam Nazar
GAM040 – ECU Bolt Shoulder Repair on Superlynx 300 MK 100	DRAS Documentations	Ir Nizam Nazar
GAM041 – Panel Fairing, LH Repair on Superlynx 300 MK 100	DRAS Documentations	Ir Nizam Nazar
GAM053 - Installation of Baggage Compartment Floor Mat on AW139	Documentations	Ir Nizam Nazar
GAM249 - Modification of Flir Lower Panel on AW139	Documentations	Ir Nizam Nazar
GAM252 - Installation of AirAsia Livery on A330-343	Documentations	Ir Nizam Nazar
GAM255 - Installation of GoPro Recording Systems on AS350B2	Documentations, Drawings, Justification	Ir Nizam Nazar
GAM257 - Installation of Data Plate, Exterior and Interior Markings on R66	Documentations	Ir Nizam Nazar
GAM259 - Installation of IFE Display Unit Placards on A330-343	Documentations	Ir Nizam Nazar
GAM262 - Hoist Variable Speed Controller Repair on AS555SN Fennec	DRAS Documentations	Ir Nizam Nazar
GAM274 - Altimeter Alarm Unit Repair on AS555SN Fennec	DRAS Documentations	Ir Nizam Nazar
GAM282 - Alternate Part Number for Flexible on Duct Superlynx 300 MK 100	Documentations	Ir Nizam Nazar
GAM283 - Alternate Part Number for Rear Fuselage Insert on Superlynx 300 MK 100	Documentations	Ir Nizam Nazar
GAM284 - Alternate Part Number for Firewall Rubberseal and Exhaust Duct Seal on Superlynx 300 MK 100	Documentations	Ir Nizam Nazar
GAM285 - Alternate Part Number for Cyclic Stick Boot on Superlynx 300 MK 100	Documentations	Ir Nizam Nazar
GAM286 - Alternate Part Number for Cabin Roof Gasket on Superlynx 300 MK 100	Documentations	Ir Nizam Nazar
GAM281 - Demodification of KR87 ADF, KRA-10A RAD ALT, CDX-FM657 CD Player and GMX200 Systems on EC120B	Documentations, Drawings, Aircraft Visit, Ground Test, Justification	Ir Nizam Nazar
GAM288 - Installation of G5 Electronic Flight Instrument on Piper PA-34-220T	Documentations, Drawings, Aircraft Visit, Ground Test, Justification	Ir Nizam Nazar
GAM317 - Installation of Airborne LIDAR Survey System on Bell 206L-4	Documentations, Drawings, Aircraft Visit, Justification	Ir Nizam Nazar
GAM315 - Installation of Dual HF on DHC6-300	Aircraft Visit, Study	Ir Nizam Nazar
GAM146 - Removal of Flir 6.4" Display and KX 165 No.2 and Installation of GTN 750Xi on Leonardo S.p.A A109E	Drawing	Ir Nizam Nazar
GAM147 - Removal of KT71 and Installation of GTX 335R on Leonardo S.p.A A109E	Drawing	Ir Nizam Nazar
GAM148 - Removal of AI-804CA and Installation of MD302 Standby on Leonardo S.p.A A109E	Drawing	Ir Nizam Nazar
GAM149 - Removal of DF931 System and Installation of DF935 System on Leonardo S.p.A A109E	Drawing	Ir Nizam Nazar
GAM256 - Installation of Seatray and Cover Seat on on Leonardo S.p.A AW139	Mockup, Aircraft Visit	Ir Nizam Nazar
Audit DGTA 2023	Filing, Document error checking, Job completeness checking	Muzrim

Training involved	Instructor
Protégé Soft Skill	Various
EWIS	Hj. Idrus
PART 21	Ir Nizam Nazar
PART 23,25,27,29 Regulations	Ir Nizam Nazar
Garmin GTN & GTR	En. Jamil Samsudin
Safety Management System	En. Rustam