

AD/SB ID: 11736

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: TEXTRON CESSNA 208 - SERVICE LETTER - AIR CONDITIONING - AC DRIVE ASSEMBLY REPLACEMENT

Title/Subject: CAL-21-02 NEW ISSUE

AD/SB ID: 11736

Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PSL	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PSM	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PSN	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PSO	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PSP	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PSQ	Not Applicable	-		0	-	-	NOT APPLICABLE	