



LEONARDO MALAYSIA SDN.BHD.

WORK CARD

SERVICE ORDER NUMBER: 90025566

WORKCARD NUMBER: 2022/31763/004-06

TITLE: EASA AD 2018-0130 ISSUED: 18 JUNE 2018 (ASB139-520 DATE: APRIL 26, 2018 REV. : /) - ATA 62 - MAIN ROTOR BLADE TIP CAP RECURRENT INSPECTION

CUSTOMER: LEONARDO HELICOPTER ITALY (LHI)

REGISTRATION: 9M-664	SERIAL NUMBER: 31763	#1 ENGINE	SERIAL NUMBER: 300:40	#2 ENGINE	SERIAL NUMBER: 300:40	APU	SERIAL NUMBER: N/A
AIRFRAME HOURS:	LANDINGS: 838	HOURS: 300:40	PCE-KB1931	HOURS: 300:40	PCE-KB1885	HOURS: 300:40	HOURS: N/A

NO	SOURCE	TASK / REFERENCE	REMARKS	MECHANIC SIGN	* AH SIGN & STAMP	DATE
----	--------	------------------	---------	---------------	-------------------	------

NOTE: FOR FIGURE(S), REFER TO IETP / ENGINE MANUAL / AD / SB.

ACCOMPLISHMENT INSTRUCTIONS

1	-	IN ACCORDANCE WITH AMP DM 39-A-00-20-00-00A-120A-A, PREPARE THE HELICOPTER ON GROUND FOR A SAFE MAINTENANCE. DISCONNECT THE BATTERY, ALL ELECTRICAL POWER SOURCES AND/OR THE EXTERNAL POWER SUPPLY.	SATISFACTORY NIL FINDINGS	<i>[Signature]</i>	<i>[Signature]</i>	15/11/22
2	-	PUT THE PLATFORM (GG-01-00), OR AN APPROVED ALTERNATIVE, ADJACENT TO THE LEFT SIDE OF THE FUSELAGE AND GAIN ACCESS TO THE AFFECTED MRB P/N 3GG210A00131.	SATISFACTORY NIL FINDINGS	<i>[Signature]</i>	<i>[Signature]</i>	15/11/22
3	-	WARNING THE HAMMER TAPPING INSPECTION MUST BE PERFORMED ONLY BY APPROPRIATELY QUALIFIED PERSONNEL IN ACCORDANCE WITH THE NATIONAL AVIATION REGULATION.	-	-	-	-

PARTS / MATERIAL USED / COMPONENT CHANGE RECORD HAVE BEEN RAISED AND CALIBRATED / SPECIAL TOOLS RECORD SHEET HAVE BEEN RAISED AND ATTACHED.

* APPROVAL HOLDER HAVE VERIFIED THAT ALL TOOLS, EQUIPMENT AND OTHER EXTRANEOUS PART OF MATERIALS ARE CLEARED AND ALL TASKS OR INSPECTIONS HAVE BEEN CARRIED OUT TO THE REQUIRED STANDARD. TASK HAS BEEN PERFORMED I.A.W MAINTENANCE MANUAL SPECIFIED IN WORKPACK INDEX LM/QA/GEN/01.

Form No: LM/QA/GEN/63
Issue 1, Rev. 1
Date: 05 Jul 2022