| SERVICE BULLETINS - AIRFRAME | | | | | | | | |
|--|--|---|---|---|---|------------------|---|--|
| □ MTL-21-02, NEW ISSUE AIR CONDITIONING - ELECTRIC HEATER THERMAL FUSE REPLACEMENT | | - | - | - | - | NOT APPLICABLE ₽ | i | |

| G | General Config List Aircraft List Task List Linked To BOM | | | | | | | | | | | | |
|----|---|----------|--------|--------------|---------|-----------|----------|-------------------|----------|--|--|--|--|
| @ | Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status | ₽ | | | | |
| ď | 9M-PTA | | - | | 0 | - | - | NOT APPLICABLE | T | | | | |
| ď | 9М-РТВ | | - | | 0 | - | - | NOT APPLICABLE | i | | | | |
| ₽° | 9M-PTC | | - | | 0 | - | - | NOT APPLICABLE | i | | | | |
| ₽° | 9M-PTD | | - | | 0 | - | - | NOT APPLICABLE | i | | | | |
| ₽° | 9M-PTE | | - | | 0 | - | - | NOT APPLICABLE | iii | | | | |

