

Aircraft Registration: 9M-PTA Date of Values: 15/12/2021 | Airframe: 5926.11 Save to template Close Update

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users											
With Selected							Show N/A	Add SB	Sortable		
Repetitive SBs [View All]											
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
SERVICE BULLETINS - AIRFRAME											
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	25/09/2021 ↗	24/09/2022 ↗	283 days +	Complete ↗
Standard SBs [View All]											
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status	
SERVICE BULLETINS - AIRFRAME											
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	-	CANCELLED ↗

Aircraft Registration: 9M-PTB Date of Values: 10/12/2021 | Airframe: 5423.41 Save to template Close Update

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users											
With Selected							Show N/A	Add SB	Sortable		
Repetitive SBs [View All]											
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
SERVICE BULLETINS - AIRFRAME											
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	23/07/2021 ↗	22/07/2022 ↗	219 days +	Complete ↗
Standard SBs [View All]											
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status	
SERVICE BULLETINS - AIRFRAME											
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	-	CANCELLED ↗

Aircraft Registration: 9M-PTC Date of Values: 15/12/2021 | Airframe: 3994.17 Save to template Close Update

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users											
With Selected							Show N/A	Add SB	Sortable		
Repetitive SBs [View All]											
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
SERVICE BULLETINS - AIRFRAME											
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	22/10/2021 ↗	21/10/2022 ↗	310 days +	Complete ↗
Standard SBs [View All]											
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status	
SERVICE BULLETINS - AIRFRAME											
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	-	CANCELLED ↗

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users											
With Selected						Show N/A Add SB Sortable					
Repetitive SBs [View All]											
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	30/08/2021 ↗	02/09/2022 ↗	261 days +	Complete ↗
Standard SBs [View All]											
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status	
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	CANCELLED ↗	
SERVICE BULLETINS - AIRFRAME											

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users											
With Selected						Show N/A Add SB Sortable					
Repetitive SBs [View All]											
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	26/07/2021	01/08/2022 ↗	229 days +	Complete ↗
Standard SBs [View All]											
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status	
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	CANCELLED ↗	
SERVICE BULLETINS - AIRFRAME											