

Aircraft Registration: 9M-PTA Date of Values: 15/12/2021 | Airframe: 5926:11

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected Show N/A Add SB Sortable

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	25/09/2021 ↗	24/09/2022 ↗	283 days +	Complete ↗

Standard SBs [View All]

			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>				SB NO. 13526 NEW ISSUE - ENGINE NO. 1 TURBOPROP ENGINE - ACCESSORY GEARBOX GEARSHAFT DRIVE - REPLACEMENT/MODIFICATION		-	-	-	-	PARTS IS FULLY USED ↗

Aircraft Registration: 9M-PTB Date of Values: 10/12/2021 | Airframe: 5423:41

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected Show N/A Add SB Sortable

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	23/07/2021 ↗	22/07/2022 ↗	219 days +	Complete ↗

Standard SBs [View All]

			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>				SB NO. 13526 NEW ISSUE - ENGINE NO. 1 TURBOPROP ENGINE - ACCESSORY GEARBOX GEARSHAFT DRIVE - REPLACEMENT/MODIFICATION		-	-	-	-	PARTS IS FULLY USED ↗

Aircraft Registration: 9M-PTC Date of Values: 15/12/2021 | Airframe: 3994:17

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected Show N/A Add SB Sortable

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	22/10/2021 ↗	21/10/2022 ↗	310 days +	Complete ↗

Standard SBs [View All]

			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>				SB NO. 13526 NEW ISSUE - ENGINE NO. 1 TURBOPROP ENGINE - ACCESSORY GEARBOX GEARSHAFT DRIVE - REPLACEMENT/MODIFICATION		-	-	-	-	PARTS IS FULLY USED ↗

- General
- Log Book
- Inspections
- Components
- Airframe
- Engine 1
- Engine 2
- Modifications
- ADs
- SBs
- Flight History
- Documents
- SORs
- Jobs
- History
- Notes
- Rates
- Users

With Selected Show N/A Add SB Sortable

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	30/08/2021 ↗	02/09/2022 ↗	261 days +	Complete ↗

Standard SBs [View All]

			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>				SB NO. 13526 NEW ISSUE - ENGINE NO. 1 TURBOPROP ENGINE - ACCESSORY GEARBOX GEARSHAFT DRIVE - REPLACEMENT/MODIFICATION		-	-	-	-	PARTS IS FULLY USED ↗

- General
- Log Book
- Inspections
- Components
- Airframe
- Engine 1
- Engine 2
- Modifications
- ADs
- SBs
- Flight History
- Documents
- SORs
- Jobs
- History
- Notes
- Rates
- Users

With Selected Show N/A Add SB Sortable

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	26/07/2021	01/08/2022 ↗	229 days +	Complete ↗

Standard SBs [View All]

			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>				SB NO. 13526 NEW ISSUE - ENGINE NO. 1 TURBOPROP ENGINE - ACCESSORY GEARBOX GEARSHAFT DRIVE - REPLACEMENT/MODIFICATION		-	-	-	-	PARTS IS FULLY USED ↗