

Annex 1 - AIRWORTHINESS DIRECTIVES STATUS LIST

Helicopter type: AW139
S/N: 31763

Last Check:	
<u>TCCA:</u>	CF-2017-35
<u>EASA:</u>	2017-0239
<u>ENAC:</u>	2017/003
<u>FAA:</u>	2017-24-09

Date: 04/12/2017
Signature: Palmi

AUTHORITY	APPLICABLE AD	ISSUE DATE	TITLE	STATUS	NOTES
TCCA	CF-2012-24	02/08/2012	SECOND STAGE POWER TURBINE DISK DAMAGE	N.A.	ENGINE POST SB41056.
EASA	2006-0242-E	11/08/2006	EXHAUST - TAILPIPE ASSY LH P/N 3G7800L00131 AND TAILPIPE ASSY RH P/N 3G7800L00231 - INSPECTION	N.A.	SUPERSEDED BY EASA AD 2006-0360-E
EASA	2006-0265-CN	17/04/2013	CANCELLED: NAVIGATION SYSTEMS - MODE C AND S TRANSPONDERS -- CHECK	N.A.	NOT APPLICABLE: CANCELLATION NOTICE
EASA	2006-0357R2	19/05/2015	FUSELAGE - FRAME 5700 MIDDLE SECTION - INSPECTION	N.A.	NOT APPLICABLE: P/N NOT AFFECTED.
EASA	2006-0358R1	26/09/2011	STABILIZERS - FIN ASSEMBLY - INSPECTION/REPLACEMENT	N.A.	SUPERSEDED BY EASA AD 2011-0205
EASA	2006-0360-E	29/11/2006	EXHAUST - TAILPIPE ASSEMBLY - INSPECTION/REPAIR/REPLACEMENT	N.A.	NOT APPLICABLE: INSTALLED DIFFERENT P/N (REF. HELICOPTER LOGBOOK).
EASA	2007-0142	18/05/2007	WINDOWS - COCKPIT DOORS WINDOWS SEALING - INSPECTION/REPAIR/REPLACEMENT	N.A.	SUPERSEDED BY EASA AD 2008-0011
EASA	2007-0156	14/06/2007	COMMUNICATION - COMM UNITS & TRANSPONDERS - MODIFICATION/REPLACEMENT	N.A.	NOT APPLICABLE: MODE S TRANSPONDER NEW P/N INSTALLED (REF. HELICOPTER LOGBOOK).
EASA	2007-0256	19/09/2007	EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT	N.A.	NOT APPLICABLE: DIFFERENT EQUIPMENT INSTALLED.
EASA	2008-0011	05/06/2008	WINDOWS - COCKPIT DOORS WINDOWS AND SEALING - INSPECTION/REPAIR/REPLACEMENT/MODIFICATION	N.A.	SUPERSEDED BY EASA AD 2008-0108
EASA	2008-0108	05/06/2008	WINDOWS - COCKPIT DOORS WINDOWS REPLACEMENT	N.A.	NOT APPLICABLE PER HELICOPTER S/N: INSTALLED DIFFERENT WINDOW P/N (REF. HELICOPTER LOGBOOK).
EASA	2008-0148	05/08/2008	FUSELAGE - WIRE STRIKE PROTECTION SYSTEM (WSPS) TOP CABLE CUTTER - REWORK/REPLACEMENT	N.A.	KIT NOT INSTALLED
EASA	2008-0157	13/08/2008	FUSELAGE - TAIL BOOM ASSEMBLY - INSPECTION / REPAIR / REPLACEMENT	N.A.	SUPERSEDED BY EASA AD 2009-0198-E
EASA	2009-0042	25/02/2009	ELECTRICAL POWER - GENERATOR CONTROL UNIT (GCU) - REPLACEMENT	N.A.	NOT APPLICABLE: INSTALLED GCU P/N 1152550-4.
EASA	2009-0124	12/06/2009	EQUIPMENT/FURNISHING - LIFESAVING SYSTEMS' D-LOCK HOOK OF THE RESCUE HOIST - INSPECTION/REPLACEMENT	N.A.	SUPERSEDED BY EASA AD 2009-0148-E
EASA	2009-0148-E	09/07/2009	EQUIPMENT/FURNISHING - D-LOCK HOOK OF THE RESCUE HOIST - INSPECTION/REMOVAL FROM SERVICE/REPLACEMENT	N.A.	SUPERSEDED BY EASA AD 2009-0179-E
EASA	2009-0179-E	11/08/2009	EQUIPMENT/FURNISHING - D-LOCK HOOK OF THE RESCUE HOIST - INSPECTION/REMOVAL FROM SERVICE/REPLACEMENT	N.A.	SUPERSEDED BY EASA AD 2009-0183-E
EASA	2009-0183-CN	11/07/2010	CANCELLATION NOTICE - EQUIPMENT FURNISHING - D-LOCK HOOK OF THE RESCUE HOIST - INSPECTION / REMOVAL FROM SERVICE / REPLACEMENT	N.A.	NOT APPLICABLE: CANCELLATION NOTICE. REFER TO FAA AD 2010-03-02

C.W. = Compliant With
N.C.W. = Not Complied With
N.A. = Not Applicable

