

SUMMARY WORK ORDER SIGNOFF SHEET




CUSTOMER	A/C Registration	A/C MSN	Work Order No
KIHUAT TIMBER (M) SDN. BHD.	9M-LKE	8297	8297000008

MI No: AS350B3-AIRCRAFT GENERAL VERIFICATION **MI Title : AIRCRAFT GENERAL VERIFICATION**
Work Description :

GENERAL VERIFICATION TO BE CARRIED OUT ON AIRCRAFT OR COMPONENT AS FOLLOWS:

- A) CLEAR OF ALL TOOLS, EQUIPMENT AND ANY EXTRANEIOUS PARTS OR MATERIAL, AND
 B) ALL ACCESS PANELS REMOVED HAVE BEEN DULY REFITTED.

Life	N/A	Work Card	N/A
Work Card Task Reference			N/A

Task n°	Due at	Dup Insp	Tech Sign	Eng Sign	Eng Stamp	Date	Remarks/Action Taken
Task n° : LKE0016 AS350B3 P/N : AS350B3 S/N : 8297	N/A	N/A				12-09-19	CARRIED OUT, FOUND SATISFACTORY.

MI No: EASB 63.00.32 <300FH
MI Title : MAIN ROTOR DRIVE – ENGINE/MGB DRIVE LINE - CHECK OF THE MGB/ENGINE COUPLING
Work Description :

This ALERT SERVICE BULLETIN consists in:




Performing a visual inspection for bolts, nuts and pins on the 2 couplings:

- equipped MGB drive shaft / flexible coupling / engine flange,
- equipped MGB drive shaft / flexible coupling / drive pulley.

Comply with paragraph 3. before the next flight from receipt of this ALERT SERVICE BULLETIN, issued on the date indicated in the page footer.

- If the bolts, nuts and pins are in place and correctly installed:
 - . Complete Appendix 4.A. and send it to Airbus Helicopters.
 - . Perform the final steps as per paragraph 3.B.3.
- If one or more bolts, nuts or pins are not in place or incorrectly installed:
 - . Stop flights.
 - . Contact the Airbus Helicopters Technical Support Department by:
 - .. E-mail: support.technical-dyncomp.ah@airbus.com
 - .. Keycopter: https://keycopter.airbushelicopters.com
 - .. Fax: +33 (0)4.42.85.99.66.
 - . Complete Appendix 4.A. and send it to Airbus Helicopters.

Life	N/A	Work Card	EASB 63.00.32
Work Card Task Reference			AMM 60-00-00, 3-1

Task n°	Due at	Dup Insp	Tech Sign	Eng Sign	Eng Stamp	Date	Remarks/Action Taken
Task n° : LKE0017 AS350-ENGINE-TO-MGB COUPLING P/N : 63-10 S/N : 8297	N/A	N/A				12-09-19	CARRIED OUT, FOUND SATISFACTORY.

"Certifies that the work specified, except as otherwise specified was carried out i.a.w CAAM Part 145 and in that respect the aircraft/ aircraft component is considered ready to release to service."