



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GFC 600 Owner and Operators
DATE: December 1, 2021
SUBJECT: Vertically Mounted GTA 82 Support Bracket
CERTIFICATION AUTHORIZATION: STC SA01844WI

COMPLIANCE

Recommended: Garmin recommends compliance with this service bulletin within the next 100 hours or the next annual inspection whichever occurs first.

PURPOSE

A new support bracket improves the stiffness of the GTA mounting structures and prevents the possibility of premature fatigue failure when subjected to long duration exposure to vibration.

PRODUCTS AFFECTED

GTA 82 units installed per the GFC 600 Installed Manual Addendum TBM 700/700N (190-01937-08) Revision 4 are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.